




TRULIV NAVALUR
CONSTRUCTION UPDATES – MARCH 2024



North Side Elevation



South Side Elevation



East Side Elevation



West Side Elevation





Interiors & Furniture's Work



Home Appliances




CP and Sanitary Fittings Fixing Work Completed



Corridor Work Completed



Lift Work Completed



Terrace Work Completed



Electrical Meter Room Work Completed



INFRASTRUCTURE DEVELOPMENT PROGRESS PHOTOS



External Paver Block Laying Work In Progress



DG Fixing Work Completed



Transformer Yard Work Completed



External Waterproofing Work Completed



*Thank
you!*