



D'ELITE

CONSTRUCTION UPDATE PHOTOS -APRIL 2024



Southeast Elevation



Westside Elevation



Northside Elevation



Eighth Floor Internal Door Fixing Work In Progress




Window Grill Work Completed -Upto 10th Floor



Internal Flats Painting Work In Progress



Basement Plumbing Work In Progress



10th Floor Low Terrace Landscape Work In Progress



Stilt Floor Ceiling Painting Work In Progress



WTP Pump Room Erection Work In Progress



AC Service Slab Handrail Work Completed



Staircase Handrail Work In Progress



Lift Granite Gladding Work In Progress



*Thank
you!*