





DRAASTRA Construction update photos – July 2025







TOP VIEW









Main building – Pour 1 1st lift Column Reinforcement work (99/127 no's)







Main building – Pour 1 1st lift column shuttering work (94/127 no's)







Main building – Pour 1 1st lift column concrete completed (94/127 no's)







Main building – Pour 01 DPC protective plastering work completed







Main building – Pour 1 basement block work completed







Main building – Pour 01 back filling work completed.







Main building – Pour 01 back filling consolidation work completed.







Main building – Pour 01 back filling dressing work completed.







Main building – Pour 1 grade slab LDPE sheet laying & reinforcement work completed







Main building – Pour 1 grade slab concrete completed









Main building – Pour 1 stilt floor 2nd lift column reinforcement completed







Main building – Pour 1 stilt floor 2nd lift column shuttering completed







Main building – Pour 1 stilt floor 2nd lift column concrete completed







Main building – Pour 01 Stilt floor Roof slab beam bottom and Slab Shuttering work in progress







Main building – Pour 01 Ramp shuttering and Reinforcement work in progress







Main building – Core wall 1st lift concrete 2 no's completed (3/3 no's)







Main building – Pour 03 & 04 plinth beam shuttering & concrete work completed







Main building – Pour 04 & 05 RC wall shuttering work completed







Main building – Pour 04 & 05 RC wall concrete work completed







Main building – Pour 04 Plinth beam PCC bottom soil levelling work completed.







Main building – Pour 04 Plinth beam PCC preparation work completed









Main building – Pour 04 Plinth beam Below ATT & PCC work completed .







Main building – Pour 04 Plinth beam PCC and Reinforcement work completed.







Main building – Pour 04 Plinth beam PCC and Reinforcement work completed.







Main building – Pour 04 Plinth beam concrete completed









STP-2nd lift Reinforcement work completed.







 $STP-2^{nd}$ lift wall shuttering work completed







STP-2nd lift Puddle flange & Sleeve fixing work completed







 $STP-2^{nd}$ lift wall concrete completed









STP wall external water proofing work in progress.









STP North and south side back filling work completed.







STP – shoring removal work completed







STP Cover slab shuttering and Reinforcement work completed







STP Cover slab concrete work completed







STP back filling work completed







UG sump cover slab reinforcement work completed.








UG sump cover slab concrete work completed.







UG Sump – Staircase concrete work completed







UG sump external wall water proofing work completed







Tower crane Excavation and PCC work completed.





Thank you!