

DRA ASTRA


CONSTRUCTION UPDATE PHOTOS – DECEMBER 2025






MASTER PLAN

TOP VIEW



TOP VIEW



SOUTHWEST ELEVATION



NORTHWEST ELEVATION





SOUTHEAST ELEVATION



SOUTHWEST ELEVATION



Main building – Stilt floor Blockwork in progress.



Main building – Pour 1 – 2nd floor roof slab shuttering and reinforcement completion.



Main building – Pour 1 – 2nd floor roof slab concrete work completion.



Main building – Pour 2 – 2nd floor column reinforcement and shuttering work completed.



Main building - Pour 2 - 2nd floor column concrete work completed.



Main building – Pour 2 – 2nd floor roof slab shuttering and reinforcement completion.



Main building – Pour 2 – 2nd floor roof slab concrete work completion



Main building – 3rd floor column reinforcement work in progress (100 Nos / 125 Nos)



Main building – 3rd floor column shuttering work in progress (74 Nos / 125 Nos)



Main building – 3rd floor column concrete work progress (74 Nos / 125 Nos)



Sales office blockwork and Electrical work completed.



Sales office plastering work completed.



Sales office Tiling work completed.



Sales office false ceiling work in progress.



Sales office Putty work in progress.



*Thank
you!*