



Content

- ❖ Master Plan
- ❖ Structure –Progress Status & Photos
 - ✓ Shell & Core
 - ✓ Block Work
 - ✓ Plastering
- ❖ Finishing –Progress Status & Photos
 - ✓ Toilet Waterproofing
 - ✓ Tile Laying
 - ✓ Painting
 - ✓ MEP Work
 - ✓ Upvc Windows
 - ✓ Joinery
- ❖ External Development

STRUCTURE - PROGRESS STATUS & PHOTOS

DRA ASTRA			
PROGRESS STATUS			
S.No	Activity	Block -01	Remarks
1	Excavation	Completed	
2	Foundation	Completed	
3	Plinth Beam	Completed	
4	Back Filling	Completed	
5	Stilt Floor -Column	Completed	
6	Stilt Floor Roof Slab	Completed	
7	Block Work	Work in progress	
8	First Floor		
	Column	Completed	
	Roof Slab	Completed	
	Block Work	Work in progress	
	Plastering -Internal		
9	Second Floor		
	Column	Completed	
	Roof Slab	Completed	
	Block Work	Completed	
	Plastering -Internal		
10	Third Floor		
	Column	Completed	
	Roof Slab	Completed	
	Block Work	Work in progress	
	Plastering -Internal		
11	Fourth Floor		
	Column	Completed	
	Roof Slab	Completed	
	Block Work		
	Plastering -Internal		
12	Fifth Floor		
	Column	Completed	
	Roof Slab	Completed	
	Block Work		
	Plastering -Internal		
13	Above Terrace		
	Parapet		
	OHT		
	LMR		
	SHR		



MASTER PLAN

TOP VIEW - FIFTH FLOOR POUR 1



SOUTHWEST SIDE ELEVATION



NORTH WEST SIDE ELEVATION



SOUTHEAST SIDE ELEVATION



SOUTHWEST SIDE ELEVATION



Main building – 4th floor roof Pour 1 electrical & Reinforcement work completed.



Main Building - 4th floor roof Pour 1 roof slab concrete completed



Main building – 5th floor column Pour 1 Reinforcement and concrete work completed



Main Building - 5th floor roof Pour 1 roof slab shuttering & Reinforcement work completed



Main Building - 5th floor roof Pour 1 roof slab electrical completed



Main Building - 5th floor roof Pour 1 roof slab concrete completed



Main Building – 6th floor Pour 1 column reinforcement work in progress.



Main building – 4th floor Pour 2 column concrete work completed.



Main building – 4th floor roof Pour 2 shuttering & Reinforcement work completed.



Main Building - 4th floor roof Pour 2 roof slab electrical work completed



Main Building – 4th floor roof Pour 2 roof slab concrete completed



Main building – 5th floor column Pour 2 Reinforcement and concrete work in progress.





Main building – 2nd floor lintel above blockwork in progress.



Main building – 3rd floor sill level blockwork in progress.



Main building – 2nd floor Electrical wall chasing work in progress.



*Thank
you!*