

DRA ASTRA

CONSTRUCTION UPDATE PHOTOS – JANUARY 2026



Content

- ❖ Master Plan
- ❖ Structure –Progress Status & Photos
 - ✓ Shell & Core
 - ✓ Block Work
 - ✓ Plastering
- ❖ Finishing –Progress Status & Photos
 - ✓ Toilet Waterproofing
 - ✓ Tile Laying
 - ✓ Painting
 - ✓ MEP Work
 - ✓ Upvc Windows
 - ✓ Joinery
- ❖ External Development

STRUCTURE - PROGRESS STATUS & PHOTOS

| DRA ASTRA | | | |
|-----------------|-----------------------|------------------|---------|
| PROGRESS STATUS | | | |
| S.No | Activity | Block | Remarks |
| 1 | Excavation | Completed | |
| 2 | Foundation | Completed | |
| 3 | Plinth Beam | Completed | |
| 4 | Back Filling | Completed | |
| 5 | Stilt Floor -Column | Completed | |
| 6 | Stilt Floor Roof Slab | Completed | |
| 7 | Block Work | Work in progress | |
| 8 | First Floor | | |
| | Column | Completed | |
| | Roof Slab | Completed | |
| | Block Work | Work in progress | |
| | Plastering -Internal | | |
| 9 | Second Floor | | |
| | Column | Completed | |
| | Roof Slab | Completed | |
| | Block Work | Work in progress | |
| | Plastering -Internal | | |
| 10 | Third Floor | | |
| | Column | Completed | |
| | Roof Slab | Completed | |
| | Block Work | | |
| | Plastering -Internal | | |
| 11 | Fourth Floor | | |
| | Column | Work in progress | |
| | Roof Slab | Work in progress | |
| | Block Work | | |
| | Plastering -Internal | | |
| 12 | Fifth Floor | | |
| | Column | | |
| | Roof Slab | | |
| | Block Work | | |
| | Plastering -Internal | | |



MASTER PLAN

TOP VIEW-FOURTH FLOOR POUR 1



TOP VIEW-FOURTH FLOOR POUR 2



SOUTHWEST SIDE ELEVATION



NORTH WEST SIDE ELEVATION



SOUTHEAST SIDE ELEVATION



SOUTHWEST SIDE ELEVATION



Main building - 3rd floor pour 1 roof slab concrete completed



Main Building - 3rd floor pour 2 roof slab concrete completed



Mainbuilding - 4th floor pour 1 column reinforcement work completed



Main building - 4th floor pour 1 column shuttering work completed



Main building – 4th floor pour 1 column concrete work completed



Main building – 4th floor roof Pour 1 shuttering work in progress



Main building – 4th floor roof Pour 1 Reinforcement work in progress



OPPO K13 5G
Chennai | 31 January 2026 at 11:28

Main building - 4th floor pour 2 column reinforcement work completed



Main building - 4th floor pour 2 column shuttering & concrete 35% work completed



Main building – 2nd floor sill level and above sill level blockwork in progress.



Sales office - Furniture's work completed



Sales office – Furniture's work completed



Sales office – External painting work in completed



Sales office – Landscape work completed



Sales office - Toilet CP & Sanitary work completed



24 January 2026 at 9:21 pm

Sales office - Toilet false ceiling work completed



*Thank
you!*