



**DRA BLISS CONSTRUCTION
SEP-2024 MONTH PROGRESS REPORT**



Front Elevation



Stilt floor entrance ramp concrete work completed



Gate painting work



Column guard fixing work completed



Letter box fixing work completed



Plumbing & Electrical signage work completed



Stilt floor carparking covering work in progress



**Internal flat Deep cleaning work
completed**



**Terrace pergola MS painting work
completed**



Terrace Pergola ACP cladding work in progress



Terrace Elevation slab work completed



Common area light fitting fixing work completed



South side external painting & Logo work completed



South side balcony Aluminum louver work completed



East side external AC service ladder work completed



East side external Shera plank work completed



*Thank
you!*