



**DRA BLISS CONSTRUCTION
AUG-24 MONTHLY PROGRESS REPORT**

Monthly progress Report August-24

S. No	Name of project	Description of the activity	Status	Remarks
1	BLISS	Completion of Stilt floor painting Work	Completed	
2		Completion of Stilt floor paver Work	Completed	
3		Completion of Stilt floor column painting Work	Completed	
4		Completion of Stilt floor CCTV Camera fixing Work	Completed	
5		Completion soil & waste plumbing pipe line Work	Completed	
6		Completion of Stilt floor glass door fixing Work	Completed	
7		Completion of toilet false ceiling Work	Completed	
8		Completion of All flats customer inspection Work	Completed	
9		Completion of Staircase painting Work	Completed	
10		Completion of Terrace plumbing line Work	Completed	
11		Completion of OHT tank ladder Work	Completed	
12		Completion of Booster pump & OTS covering work	Completed	
13		Completion of External painting work	In-Progress	
14		Completion of After CC work	In-Progress	



Front Elevation



Stilt floor carparking painting work completed



Stilt floor paver work completed



Stilt floor column painting work completed



Stilt floor CCTV camera fixing work in completed



Stilt floor lift lobby glass door fixing work completed




Stilt floor soil and waste line plumbing pipe connection work completed



Toilet false ceiling work completed



All flats customer inspection completed



Staircase area 1st coat painting work completed



Terrace plumbing pipe line work completed



Terrace OHT tank ladder work completed



**Terrace booster pump & OTS covering
work completed**



External painting work in progress



**After CC works compound wall demolition &
compound wall MS work in progress**



Stilt floor entrance ramp work in progress



**Terrace pergola MS work & Terrace
Elevation slab scaffolding work in
progress**

A large, light grey decorative graphic consisting of several overlapping, curved, ribbon-like shapes that sweep across the left side of the page.

*Thank
you!*