












STAGE COMPLICTION STATUS UP TO JULY-2024				
Sl. No	Name of Project	Description of the activity	Status	Remarks
1		Completion of Stilt Floor plastering	Completed	
2		Compound wall block work work	Completed	
3		Compound wall plastering work	Completed	
4		Compound wall primer work	Completed	
5		Enterence gate fixing	Completed	
6		1st floor internal finishing work	In-Progress	80%Completed
7	Bliss	2nd floor internal finishing work	In-Progress	90%Completed
8		3rd floor internal finishing work	In-Progress	90%Completed
9		4th floor internal finishing work	In-Progress	85%Completed
10		Terrace clay tiles	Completed	
11		External painting work	In-Progress	75%Completed
12		Extenral plumbing shaft work & chamber work	In-Progress	90%Completed
13		External Electrical chamber work	In-Progress	85%Completed







**Front Elevation** 







Stilt floor carparking concrete work completed







Stilt floor paver area WMM filling work in progress







Stilt floor ceiling 1st coat painting completed







Flats Internal primer work completed







**Toilet CP fittings fixing Work in progress** 







**Balcony flooring Tiling Work Completed** 







Balcony plumbing pipe covering Work completed







Toilet inner false ceiling Work in progress







**Balcony Hand rail work completed** 







Unit 201,202,301,302,401 flats 1<sup>st</sup> coat internal painting work completed







Terrace clay tiles work completed









External painting 1<sup>st</sup> coat east & west side work in progress









East side External plumbing Shaft plumbing pipe line work & chamber work in progress







External stilt floor Electrical earth pit chamber work in progress







**Entrance gate work completed** 













Compound wall four side work completed





Thank you!