BEENA CLOVER MONTHLY CONSTRUCTION UPDATES - AUGUST 2024











SALES OFFICE FRONT VIEW







MODEL FLAT FRONT VIEW


















SALES OFFICE GLASS FIXING WORK COMPLETED





SALES OFFICE INTERIOR WORK COMPLETED











SALES OFFICE DOOR FIXING WORK COMPLETED

















SALES OFFICE WINDOW & GRILL FIXING WORK COMPLETED



SALES OFFICE DUCTAC DIFFUSER & GRILL FIXING WORK COMPLETED













LAWN AREA HARDSCAPE WORK COMPLETED.LANDSCAPE WORK IN PROGRESS







PATHWAY PAVER BLOCK LAYING WORK IN PROGRESS














MODEL FLAT FALSE CEILING WORK COMPLETED









MODEL FLAT WINDOW & GRILL FIXING WORK COMPLETED







MODEL FLAT DOOR FIXING WORK COMPLETED









LABOUR SHED GI SHED WORK COMPLETED









LABOUR SHED TOILET & BATH TANK WORK COMPLETED







STORAGE CONTAINER FIXING WORK COMPLETED









LABOUR SHED PLUMBING WORK COMPLETED











STEEL YARD&LABOR SHED BARRICATION WORK COMPLETED











NORTH SIDE COMPOUND WALL FOOTING CONCRETE WORK IN PROGRESS









WEST SIDE COMPOUND WALLFOOTING & COLUMN CONCRETE WORK IN PROGRESS









MAIN BUILDING EARTH WORK EXCAVATION WORK COMMENCED





