



## BEENA CLOVER

**MONTHLY CONSTRUCTION UPDATES - AUGUST 2024**

## STAGE COMPLETION STATUS UP TO AUGUST 2024

S. No	Description	Status	Remarks
1	Completion of Foundation		
2	Completion of Stilt Floor Roof		
3	Completion of First Floor Roof		
4	Completion of Second Floor Roof		
5	Completion of Third Floor Roof		
6	Completion of Fourth Floor Roof		
7	Completion of Fifth Floor Roof		
8	Completion of Masonry Work		
9	Completion of Internal Plastering		
10	Completion of Internal Finishes		



**SALES OFFICE FRONT VIEW**



**MODEL FLAT FRONT VIEW**




**SALES OFFICE WALL 2<sup>ND</sup> COAT PAINTING WORK IN PROGRESS**



**SALES OFFICE GLASS FIXING WORK COMPLETED**



**SALES OFFICE INTERIOR WORK COMPLETED**




**SALES OFFICE DOOR FIXING WORK COMPLETED**





**SALES OFFICE WINDOW & GRILL FIXING WORK COMPLETED**



**SALES OFFICE DUCT AC DIFFUSER & GRILL FIXING WORK COMPLETED**



**LAWN AREA HARDSCAPE WORK COMPLETED.LANDSCAPE WORK IN PROGRESS**



**PATHWAY PAVER BLOCK LAYING WORK IN PROGRESS**



**MODEL FLAT FALSE CEILING WORK COMPLETED**



**MODEL FLAT WINDOW & GRILL FIXING WORK COMPLETED**



**MODEL FLAT DOOR FIXING WORK COMPLETED**



**LABOUR SHED GI SHED WORK COMPLETED**





**LABOUR SHED TOILET & BATH TANK WORK COMPLETED**



**STORAGE CONTAINER FIXING WORK COMPLETED**



**LABOUR SHED PLUMBING WORK COMPLETED**



**STEEL YARD&LABOR SHED BARRICATION WORK COMPLETED**



**NORTH SIDE COMPOUND WALL FOOTING CONCRETE WORK IN PROGRESS**



**WEST SIDE COMPOUND WALL FOOTING & COLUMN CONCRETE WORK IN PROGRESS**



**MAIN BUILDING EARTH WORK EXCAVATION WORK COMMENCED**



*Thank  
you!*