





# **BEENA CLOVER**

**Monthly Construction Updates – December 2024** 





#### Over all percentage of Completion

S. No	Project Code	Project Name	Saleable Area in Sqft	Cumulative% Achieved up to Dec-24	Status
1	DRA-29	Clover	2,78,615	10%	Foundation Stage







STAGE COMPLETION STATUS UP TO DECEMBER 2024							
S. No	Description	Status	% of Completion	Remarks			
1	Commencement of Foundation	Progress	80 %				
2	Commencement of Stilt Floor Roof						
3	Commencement of First Floor Roof						
4	Commencement of Second Floor Roof						
5	Commencement of Third Floor Roof						
6	Commencement of Fourth Floor Roof						
7	Commencement of Fifth Floor Roof						
8	Commencement of Masonry Work						
9	Commencement of Internal Plastering						
10	Commencement of Internal Finishes						







**Site Front View** 







### **Block-1-Top View**









## **Block-1 Column Shuttering & Concrete Work in Progress**









**Block-1-STP Excavation Work in Progress** 







**Block-2- Top View** 









**Block-2** – Footing & Column Concrete work in progress









UG Sump- Raft Reinforcement & Shuttering & Concrete Work in Progress








**Block-3- Top View** 










**Block-3- Stilt Floor Column Reinforcement & Concrete Work in Progress** 









**Block-3- Plinth Beam DPC & Protective Plastering Work in Progress** 







**Block-4- Top View** 









## **Block-4- Plinth Beam PCC & Shuttering work in Progress**









**Rain Water Tank Water Proofing Work Commenced** 









#### **Entrance Arch Footing Concrete Work Completed**









East Side Compound Wall Footing & Column Concrete Work in Progress







