



BEENA CLOVER

Monthly Construction Updates – April 2025

Over all percentage of Completion

S. No	Project Code	Project Name	Saleable Area in Sqft	Cumulative% Achieved up to April-25	Status
1	DRA-29	Clover	2,78,615	24%	Structure Stage

STAGE COMPLETION STATUS UP TO APRIL 2025

S. No	Description	Status	% of Completion	Remarks
1	Commencement of Foundation	Work In Progress	95%	Block 3&4 Completed
2	Commencement of Stilt Floor Roof	Work In Progress	50%	Block 3&4 Completed
3	Commencement of First Floor Roof	Work In Progress	50%	Block 3&4 Completed
4	Commencement of Second Floor Roof	Work In Progress	50%	Block 3 & 4 Completed
5	Commencement of Third Floor Roof	Work In Progress	25%	Block 3 Completed
6	Commencement of Fourth Floor Roof			
7	Commencement of Fifth Floor Roof			
8	Commencement of Masonry Work	Work In Progress	10%	Block-3 Work in progress
9	Commencement of Internal Plastering			
10	Commencement of Internal Finishes			



Site Top View



Site Front View



Block-1-Top View



Block-1- Pour-1-Back filling Work in Progress



Block-1-STP Wall Concrete Work in progress



Block-2- Pour 1 - Stilt Floor Pcc Work Completed



Block-3- Top View



Block-3- First Floor Block work in Progress



Block-3-Pour 2- Fourth Floor Beam Reinforcement Work in Progress



Block-4- Top View



Block-4- Pour 1- Fourth Floor Slab Shuttering Work in Progress



Block-4- Third Floor Column Shuttering & Concrete Work in Progress



Exit Arch Block Work in Progress

*Thank
you!*