



BEENA CLOVER

Monthly Construction Updates – February 2025

Over all percentage of Completion

S. No	Project Code	Project Name	Saleable Area in Sqft	Cumulative% Achieved up to Feb-25	Status
1	DRA-29	Clover	2,78,615	18%	Structure Stage

STAGE COMPLETION STATUS UP TO FEB 2025

S. No	Description	Status	% of Completion	Remarks
1	Commencement of Foundation	Work In Progress	90%	
2	Commencement of Stilt Floor Roof	Work In Progress	40%	
3	Commencement of First Floor Roof			
4	Commencement of Second Floor Roof			
5	Commencement of Third Floor Roof			
6	Commencement of Fourth Floor Roof			
7	Commencement of Fifth Floor Roof			
8	Commencement of Masonry Work			
9	Commencement of Internal Plastering			
10	Commencement of Internal Finishes			



Site Top View



Block-1-Top View



Block-1-Pour 1 Stilt Floor Column shuttering & concrete Work in Progress



Block-1-Pour 2 Sub Structure Column Concrete Work in Progress



Block-1-STP Raft Reinforcement Work in Progress



Block-2- Top View



Block-2-Pour 1&2-Stilt Floor Column Concrete work in progress



Block-2-Pour 2-Plinth Beam DPC Protective Plastering work in progress



Block-2-Pour 3-Footing PCC work in progress



Block-3- Top View



Block-3-Pour 1-Second Floor Slab Shuttering & Reinforcement Work in Progress



Block-4- Top View



**Block-4- Pour 1-First floor Slab Concrete Work Completed & Pour-2
Shuttering work in Progress**



**Exit Arch Security Cabin Column Concrete work Completed. Security
cabin Block Work in Progress**



East Side Compound Wall Block Work Completed & Coping Beam concrete Work in Progress

*Thank
you!*