



## BEENA CLOVER

Monthly Construction Updates –January 2025

## Over all percentage of Completion

S. No	Project Code	Project Name	Saleable Area in Sqft	Cumulative% Achieved up to Jan-25	Status
1	DRA-29	Clover	2,78,615	11%	Foundation Stage

STAGE COMPLETION STATUS UP TO JANUARY 2025

S. No	Description	Status	% of Completion	Remarks
1	Commencement of Foundation	Work In Progress	90 %	
2	Commencement of Stilt Floor Roof	Work In Progress	15%	
3	Commencement of First Floor Roof			
4	Commencement of Second Floor Roof			
5	Commencement of Third Floor Roof			
6	Commencement of Fourth Floor Roof			
7	Commencement of Fifth Floor Roof			
8	Commencement of Masonry Work			
9	Commencement of Internal Plastering			
10	Commencement of Internal Finishes			



**Site Front View**



**Site Full Top View**



**Block-1-Top View**



**Block-1-Pour 1 Plinth beam Pcc Work in Progress**



**Block-1-Pour 2 Footing Concrete Work in Progress**





**Block-1-STP Excavation Work in Progress**



**Block-2- Top View**



**Block-2-Pour 1&2- Backfilling & Plinth beam pcc  
work in progress**



**UG Sump- Cover slab concrete completed & Outer waterproofing Work in Progress**



**Block-3- Top View**



## **Block-3-Pour 1-Stilt Floor Roof Slab Shuttering & Reinforcement Work in Progress**



**Block-4- Top View**



**Block-4- Stilt floor column concrete Work completed & DPC work in Progress**



*Thank  
you!*