

BEENA CLOVER


CONSTRUCTION UPDATE PHOTOS – MAY 2026



Content

- ❖ Master Plan
- ❖ Structure –Progress Status & Photos
 - ✓ Shell & Core
 - ✓ Block Work
 - ✓ Plastering
- ❖ Finishing –Progress Status & Photos
 - ✓ Toilet Waterproofing
 - ✓ Tile Laying
 - ✓ Painting
 - ✓ MEP Work
 - ✓ Upvc Windows
 - ✓ Joinery
- ❖ External Development

MASTER PLAN



STRUCTURE –PROGRESS STATUS & PHOTOS

S.No	Activity	Block -01	Block -02	Block -03	Block -04
1	Excavation	Completed	Completed	Completed	Completed
2	Foundation	Completed	Completed	Completed	Completed
3	Plinth Beam	Completed	Completed	Completed	Completed
4	Back Filling	Completed	Completed	Completed	Completed
5	Stilt Floor -Column	Completed	Completed	Completed	Completed
6	Stilt Floor Roof Slab	Completed	Completed	Completed	Completed
7	First Floor				
	Column	Completed	Completed	Completed	Completed
	Roof Slab	Completed	Completed	Completed	Completed
	Block Work	Completed	Completed	Completed	Completed
	Plastering -Internal	Completed	Completed	Completed	Completed
8	Second Floor				
	Column	Completed	Completed	Completed	Completed
	Roof Slab	Completed	Completed	Completed	Completed
	Block Work	Completed	Completed	Completed	Completed
	Plastering -Internal	Completed	Completed	Completed	Completed
9	Third Floor				
	Column	Completed	Completed	Completed	Completed
	Roof Slab	Completed	Completed	Completed	Completed
	Block Work	Completed	Completed	Completed	Completed
	Plastering -Internal	Work in progress	Completed	Completed	Completed
10	Fourth Floor				
	Column	Completed	Completed	Completed	Completed
	Roof Slab	Completed	Completed	Completed	Completed
	Block Work	Work in progress	Completed	Completed	Completed
	Plastering -Internal	Work in progress	Work in progress	Completed	Completed
11	Fifth Floor				
	Column	Completed	Completed	Completed	Completed
	Roof Slab	Completed	Completed	Completed	Completed
	Block Work	Work in progress	Completed	Completed	Completed
	Plastering -Internal	Work in progress	Work in progress	Completed	Completed
12	Above Terrace				
	Parapet	Work in progress	Completed	Completed	Completed
	OHT		Work in progress	Completed	Completed
	LMR	Work in progress	Work in progress	Completed	Completed
	SHR			Completed	Completed



Block-01 – Elevation View



Block-01 – Pour-2 – 4th Floor Block Work in Progress



Block-01 – Pour-2 – 5th Floor Block Work in Progress



Block-01 – Pour-2 – 3rd Floor Plastering Work in Progress



Block-01 – Pour-1 – External Texture Work in Progress



Block-01 – Pour-1 – 1st to 4th Floor Sunken Filling work in Progress



Block-01 – Pour-1 – 3rd Floor Concealed Line work in Progress



Block-01 – Pour-1 – 1st Floor Suspended Pipe Line work in Progress



Block-01 – Mock up Flat work in Progress



Block-02 – Elevation View



Block-02 – Pour-2 – 4th Floor Plastering Work in Progress



Block-02 – Pour-2 – 5th Floor Plastering work in progress



Block-02 – Pour-2 – External Plastering work in progress



Block-02 – Pour-1 – 1st Floor Tile Laying Work.



Block-02 – Pour-1 – 2nd Floor Tile Laying Work.



Block-02 – Pour-2 – 1st to 3rd Floor Water proofing Work in Progress.



Block-03 – Elevation View



Block-03 – 1st to 5th Floor UPVC Window Fixing Work completed



Block-03 – 1st to 5th Floor Grill Fixing Work Completed



Block-03 – 4th Floor 1st Coat Painting Work Completed



Block-03 – 5th Floor Sanding Work in Progress



Block-04 – Elevation View



Block-04 – 1st & 2nd Floor Sanding work in Progress



Block-04 – 3rd Floor UPVC Window Fixing Work in Progress



Block-04 – 1st to 4th Floor Kitchen Tile Laying work Completed.



Block-04 – Terrace Floor Protective Plastering Work Completed

*Thank
you!*