

BEENA CLOVER


MONTHLY CONSTRUCTION PHOTOS – JUNE-26



Content

- ❖ Master Plan
- ❖ Structure –Progress Status & Photos
 - ✓ Shell & Core
 - ✓ Block Work
 - ✓ Plastering
- ❖ Finishing –Progress Status & Photos
 - ✓ Toilet Waterproofing
 - ✓ Tile Laying
 - ✓ Painting
 - ✓ MEP Work
 - ✓ Upvc Windows
 - ✓ Joinery
- ❖ External Development

MASTER PLAN



STRUCTURE -PROGRESS STATUS & PHOTOS

S.No	Activity	Block -01	Block -02	Block -03	Block -04
1	Excavation	Completed	Completed	Completed	Completed
2	Foundation	Completed	Completed	Completed	Completed
3	Plinth Beam	Completed	Completed	Completed	Completed
4	Back Filling	Completed	Completed	Completed	Completed
5	Stilt Floor -Column	Completed	Completed	Completed	Completed
6	Stilt Floor Roof Slab	Completed	Completed	Completed	Completed
7	First Floor				
	Column	Completed	Completed	Completed	Completed
	Roof Slab	Completed	Completed	Completed	Completed
	Block Work	Completed	Completed	Completed	Completed
	Plastering -Internal	Completed	Completed	Completed	Completed
8	Second Floor				
	Column	Completed	Completed	Completed	Completed
	Roof Slab	Completed	Completed	Completed	Completed
	Block Work	Completed	Completed	Completed	Completed
	Plastering -Internal	Completed	Completed	Completed	Completed
9	Third Floor				
	Column	Completed	Completed	Completed	Completed
	Roof Slab	Completed	Completed	Completed	Completed
	Block Work	Completed	Completed	Completed	Completed
	Plastering -Internal	Completed	Completed	Completed	Completed
10	Fourth Floor				
	Column	Completed	Completed	Completed	Completed
	Roof Slab	Completed	Completed	Completed	Completed
	Block Work	Completed	Completed	Completed	Completed
	Plastering -Internal	Work in progress	Completed	Completed	Completed
11	Fifth Floor				
	Column	Completed	Completed	Completed	Completed
	Roof Slab	Completed	Completed	Completed	Completed
	Block Work	Completed	Completed	Completed	Completed
	Plastering -Internal	Work in progress	Completed	Completed	Completed
12	Above Terrace				
	Parapet	Completed	Completed	Completed	Completed
	OHT	Work in progress	Work in progress	Completed	Completed
	LMR	Completed	Completed	Completed	Completed
	SHR		Work in progress	Completed	Completed



Block-01 – Elevation View



Block-01 – Pour-2 – 5th Floor Block Work Completed



Block-01 – Pour-2 – 4th Floor Plastering Work in Progress



Block-01 – Pour 1 5th Floor Ledge Wall Brick Work in Progress



Block-01 – Pour-1 Suspended Line Work in Progress



Block-01 – Pour-1 1st Floor Toilet Tile Laying Work in Progress



Block-01 – Pour-2 1st Floor 1st Coat Putty Work in Progress



Block-01 External Texture Work in Progress



Block-02 – Elevation View



Block-02 – Pour-2 – 5th Floor Plastering Work Completed



Block-02 – Pour-2 – External Plastering work in progress



Block-02 – Pour-1 – 4th & 5th Floor Flooring Tile Laying Work.



Block-02 – Pour-2 – Water proofing Nearing Completion.



Block-02 – Pour-1 – 1st & 2nd Floor Kitchen Granite Work in Progress.



Block-02 – Pour-2 – 1st Floor Concealed Tank Work Completed.



Block-02 – External Texture Work in Progress.



Block-03 – Elevation View



Block-03 – Common Area UPVC Window Fixing Work in Progress



Block-03 – Stilt Floor Suspended Line Work in Progress.



Block-03 – Balcony Handrail Work in Progress.



Block-03 – Lift Erection Work in Progress



Block-03 – 1st Floor Door Fixing Work in Progress



Block-03 – Staircase Handrail Work in Progress



Block-04 – Elevation View



Block-04 – 4th Floor 2nd Coat Putty work in Progress



Block-04 – 5th Floor Primer Work in Progress



Block-04 – Balcony Handrail work Completed.



Block-03 – Staircase Flooring Tile Completed

*Thank
you!*