

BEENA CLOVER


MONTHLY CONSTRUCTION UPDATES – JULY-26



Content

- ❖ Master Plan
- ❖ Structure –Progress Status & Photos
 - ✓ Shell & Core
 - ✓ Block Work
 - ✓ Plastering
- ❖ Finishing –Progress Status & Photos
 - ✓ Toilet Waterproofing
 - ✓ Tile Laying
 - ✓ Painting
 - ✓ MEP Work
 - ✓ Upvc Windows
 - ✓ Joinery
- ❖ External Development

MASTER PLAN



STRUCTURE -PROGRESS STATUS & PHOTOS

S.No	Activity	Block -01	Block -02	Block -03	Block -04
1	Excavation	Completed	Completed	Completed	Completed
2	Foundation	Completed	Completed	Completed	Completed
3	Plinth Beam	Completed	Completed	Completed	Completed
4	Back Filling	Completed	Completed	Completed	Completed
5	Stilt Floor -Column	Completed	Completed	Completed	Completed
6	Stilt Floor Roof Slab	Completed	Completed	Completed	Completed
7	First Floor				
	Column	Completed	Completed	Completed	Completed
	Roof Slab	Completed	Completed	Completed	Completed
	Block Work	Completed	Completed	Completed	Completed
	Plastering -Internal	Completed	Completed	Completed	Completed
8	Second Floor				
	Column	Completed	Completed	Completed	Completed
	Roof Slab	Completed	Completed	Completed	Completed
	Block Work	Completed	Completed	Completed	Completed
	Plastering -Internal	Completed	Completed	Completed	Completed
9	Third Floor				
	Column	Completed	Completed	Completed	Completed
	Roof Slab	Completed	Completed	Completed	Completed
	Block Work	Completed	Completed	Completed	Completed
	Plastering -Internal	Completed	Completed	Completed	Completed
10	Fourth Floor				
	Column	Completed	Completed	Completed	Completed
	Roof Slab	Completed	Completed	Completed	Completed
	Block Work	Completed	Completed	Completed	Completed
	Plastering -Internal	Completed	Completed	Completed	Completed
11	Fifth Floor				
	Column	Completed	Completed	Completed	Completed
	Roof Slab	Completed	Completed	Completed	Completed
	Block Work	Completed	Completed	Completed	Completed
	Plastering -Internal	Completed	Completed	Completed	Completed
12	Above Terrace				
	Parapet	Completed	Completed	Completed	Completed
	OHT	Completed	Completed	Completed	Completed
	LMR	Completed	Completed	Completed	Completed
	SHR	Completed	Completed	Completed	Completed




Block-01 – Elevation View



BLOCK-01 – POUR-2 – 5TH FLOOR PLASTERING WORK COMPLETED



BLOCK-01 – PARAPET PLASTERING WORK IN PROGRESS



BLOCK-01 – POUR-2 4TH FLOOR WATERPROOFING WORK IN PROGRESS



BLOCK-01 – POUR-1 4TH & 5TH FLOOR FLOORING TILE LAYING WORK IN PROGRESS



BLOCK-01 – POUR-2 4TH FLOOR WALL PUTTY WORK IN PROGRESS



BLOCK-01 ENTRANCE ARCH SECURITY CABINE SLAB WORK IN PROGRESS



Block-02 – Elevation View



BLOCK-02 – POUR-1 TERRACE WATERPROOFING WORK IN PROGRESS



BLOCK-02 – EXTERNAL TEXTURE WORK IN PROGRESS



BLOCK-02 – EXTERNAL PLASTERING WORK IN PROGRESS



BLOCK-02 – TERRACE BLOCKWORK COMPLETED.



BLOCK-02 – POUR 1 – KITCHEN COUNTER & UTILITY WALL TILE LAYING WORK COMPLETED.



BLOCK-02 – POUR-1 – UPTO 4TH FLOOR UPVC WINDOW FIXING WORK COMPLETED.




BLOCK-02 – POUR-2 – 3RD FLOOR LEDGE WALL PLASTERING COMPLETED & 5TH FLOOR
CONCEALED TANK FIXING COMPLETED.



BLOCK-02 – 4TH & 5TH FLOOR SUSPENDED PIPELINE WORK IN PROGRESS.



BLOCK-02 – POUR 2 1ST & 2ND FLOOR WALL PUTTY WORK IN PROGRESS.



BLOCK-02 POUR 2 1ST FLOOR TILE LAYING WORK IN PROGRESS.



BLOCK-02 POUR 1 1ST TO 3RD FLOOR PRIMER WORK IN PROGRESS.



Block-03 – Elevation View



BLOCK-03 – LIFT ERECTION WORK IN PROGRESS



BLOCK-03 – LIFT GRANITE CLADDING COMPLETED.



BLOCK-03 – UPTO 3RD FLOOR DOOR FIXING WORK COMPLETED.



BLOCK-03 – OTS COVERING WORK IN PROGRESS



BLOCK-04 – ELEVATION VIEW



BLOCK-04 – STILT FLOOR CEILING PUTTY & PRIMER WORK IN PROGRESS



BLOCK-04 – 4TH & 5TH FLOOR CORRIDOR PRIMER WORK IN PROGRESS



BLOCK-04 – 1ST & 2ND FLOOR DOOR FIXING WORK IN PROGRESS



BLOCK-04 – 1ST & 2ND FLOOR WINDOW GRILL FIXING WORK COMPLETED



BLOCK-04 – STAIRCASE CEILING & WALL PUTTY WORK IN PROGRESS



BLOCK-04 – DUCT PAINTING WORK COMPLETED.



BLOCK-04 – LIFT ERECTION WORK IN PROGRESS

*Thank
you!*