



BEENA CLOVER

Monthly Construction Updates – July 2025

STAGE COMPLETION STATUS UP TO JULY 2025

S. No	Description	Status	Remarks
1	Completion of Foundation	Completed	
2	Completion of Stilt Floor Roof	Progress	
3	Completion of First Floor Roof	Progress	
4	Completion of Second Floor Roof	Progress	
5	Completion of Third Floor Roof	Progress	
6	Completion of Fourth Floor Roof	Progress	
7	Completion of Fifth Floor Roof	Progress	
8	Completion of Masonry Work	Progress	
9	Completion of Internal Plastering	Progress	
10	Completion of Internal Finishes		



Site Front View



Block-1-Top View



Block-1- Pour-1- First Floor Slab Reinforcement Completed



Block-1- Pour-2- Plinth Beam Back Filling Completed



Block-1- Pour 3-Soil Filling work in progress



Block-2- Top View



Block-2- Pour 1 – Second Floor Column Concrete Work in Progress



Block-2- Pour 1 – Third Floor Slab Shuttering Work in Progress



Block-2-Pour 2- Soil Filling Work in progress



Block-3- Elevation View



Block-3 Above Terrace Activity Work in Progress



Block-3- First Floor Wall Plastering work in Progress



Block-3 Third Floor Kitchen Counter Slab Concrete work completed



Block-3 Fourth Floor Block Work in Progress



Block-3 Fifth Floor Blockwork Layout Commenced



Block-3 Terrace Floor Parapet Blockwork in Progress



Block-4- Elevation View



Block-4 Above Terrace Activity Work in Progress



Block-4- First Floor Lintel Concrete work in Progress



Block-4 Second Floor Sill Reinforcement work in progress



Block-4- Third Floor Block Work in progress



Exit Arch

*Thank
you!*