

BEENA CLOVER


MONTHLY CONSTRUCTION UPDATES – MARCH-26



Content

- ❖ Master Plan
- ❖ Structure –Progress Status & Photos
 - ✓ Shell & Core
 - ✓ Block Work
 - ✓ Plastering
- ❖ Finishing –Progress Status & Photos
 - ✓ Toilet Waterproofing
 - ✓ Tile Laying
 - ✓ Painting
 - ✓ MEP Work
 - ✓ Upvc Windows
 - ✓ Joinery
- ❖ External Development

MASTER PLAN



STRUCTURE -PROGRESS STATUS & PHOTOS

S.No	Activity	Block -01	Block -02	Block -03	Block -04
1	Excavation	Completed	Completed	Completed	Completed
2	Foundation	Completed	Completed	Completed	Completed
3	Plinth Beam	Completed	Completed	Completed	Completed
4	Back Filling	Completed	Completed	Completed	Completed
5	Stilt Floor -Column	Completed	Completed	Completed	Completed
6	Stilt Floor Roof Slab	Completed	Completed	Completed	Completed
7	First Floor				
	Column	Completed	Completed	Completed	Completed
	Roof Slab	Completed	Completed	Completed	Completed
	Block Work	Completed	Completed	Completed	Completed
	Plastering -Internal	Completed	Completed	Completed	Completed
8	Second Floor				
	Column	Completed	Completed	Completed	Completed
	Roof Slab	Completed	Completed	Completed	Completed
	Block Work	Completed	Completed	Completed	Completed
	Plastering -Internal	Work in progress	Completed	Completed	Completed
9	Third Floor				
	Column	Completed	Completed	Completed	Completed
	Roof Slab	Completed	Completed	Completed	Completed
	Block Work	Work in progress	Completed	Completed	Completed
	Plastering -Internal	Work in progress	Work in progress	Completed	Completed
10	Fourth Floor				
	Column	Completed	Completed	Completed	Completed
	Roof Slab	Completed	Completed	Completed	Completed
	Block Work	Work in progress	Completed	Completed	Completed
	Plastering -Internal	Work in progress	Work in progress	Completed	Completed
11	Fifth Floor				
	Column	Completed	Completed	Completed	Completed
	Roof Slab	Work in progress	Completed	Completed	Completed
	Block Work	Work in progress	Work in progress	Completed	Completed
	Plastering -Internal	Work in progress	Work in progress	Completed	Completed
12	Above Terrace				
	Parapet	Work in progress	Work in progress	Completed	Completed
	OHT		Work in progress	Completed	Completed
	LMR		Work in progress	Completed	Completed
	SHR			Completed	Completed



Block-01 – Elevation View



Block-01 – Pour-2 – Terrace Floor Slab Shuttering & Reinforcement Work Nearing Completion



Block-01 – Pour-2 – Second Floor Block Work Completed



Block-01 – Pour-2 – Third Floor Block work in Progress



Block-01 – Pour-1 – Fourth Floor Plastering work in Progress



Block-01 – Pour-1 – Fifth Floor Plastering work in Progress



Block-02 – Elevation View



Block-02 – Pour-2 – Fourth Floor Block Work Completed.



Block-02 – Pour-2 – Fifth Floor Block work in progress



Block-02 – Pour-2 – Second Floor Plastering Work Completed



Block-02 – Pour-2 – Third Floor Toilet Plastering work in progress



Block-02 – Pour-1 – First Floor Concealed Tank & Ledge Wall Brick Work in Progress.



Block-02 – Above Terrace Work in Progress



Block-03 – Elevation View



Block-03 – First Floor 2nd Coat Putty work in progress



Block-03 – Fifth Floor Flooring Tile Laying work in Progress



Block-03 – Terrace Waterproofing work in Progress



Block-04 – Elevation View



Block-04 – Second Floor Toilet Tile Laying work in Progress



Block-04 – Terrace Floor Waterproofing Preparation work in Progress

*Thank
you!*