



BEENA CLOVER

Monthly Construction Updates – November 2025

STAGE COMPLETION STATUS UP TO NOVEMBER 2025

S. No	Description	Status	Remarks
1	Completion of Foundation	Completed	
2	Completion of Stilt Floor Roof	Completed	
3	Completion of First Floor Roof	Progress	
4	Completion of Second Floor Roof	Progress	
5	Completion of Third Floor Roof	Progress	
6	Completion of Fourth Floor Roof	Progress	
7	Completion of Fifth Floor Roof	Progress	
8	Completion of Masonry Work	Progress	
9	Completion of Internal Plastering	Progress	
10	Completion of Internal Finishes		



Site Front View



Block-1- Elevation View



Block-1- Pour-2-First Floor Column Concrete Work In Progress



Block-1- Pour 1-Fourth Floor Slab Concrete Work Completed



Block-1- Pour 1-Second Floor Block Work In progress



Block-2- Elevation View



Block-2-Pour 1- First Floor Plastering Work in Progress



Block-2- Pour 2 –First Floor Block Work in Progress



Block-2-Pour 2- Third Floor Slab Reinforcement Work in progress




Block-2- Pour 1 – Fifth Floor Chips Packing Work in Progress



Block-3 – Elevation View



Block-3 Third floor Toilet Concealed Tank Brick Work in Progress



Block-3 Fourth Floor Suspended Pipeline Work in Progress



Block-3- Fifth Floor Waterproofing Protective Plastering Work Completed



Block-3- External-North Side Texture work in Progress



Block-4- Elevation View



Block-4- First Floor Suspended Pipeline Work in Progress



Block-4- Second Floor Waterproofing Work in Progress



Block-4- Fourth Floor Plastering work Completed



Block-4 Fifth Floor Plastering Work in Progress



Block-4 Duct Plastering Work in Progress

Thank
you!