

BEENA CLOVER

MONTHLY CONSTRUCTION UPDATES – DECEMBER-25



Content

- ❖ Master Plan
- ❖ Structure –Progress Status & Photos
 - ✓ Shell & Core
 - ✓ Block Work
 - ✓ Plastering
- ❖ Finishing –Progress Status & Photos
 - ✓ Toilet Waterproofing
 - ✓ Tile Laying
 - ✓ Painting
 - ✓ MEP Work
 - ✓ Upvc Windows
 - ✓ Joinery
- ❖ External Development

MASTER PLAN



STRUCTURE -PROGRESS STATUS & PHOTOS

S.No	Activity	Block -01	Block -02	Block -03	Block -04
1	Excavation	Completed	Completed	Completed	Completed
2	Foundation	Completed	Completed	Completed	Completed
3	Plinth Beam	Completed	Completed	Completed	Completed
4	Back Filling	Completed	Completed	Completed	Completed
5	Stilt Floor -Column	Completed	Completed	Completed	Completed
6	Stilt Floor Roof Slab	Completed	Completed	Completed	Completed
7	First Floor				
	Column	Completed	Completed	Completed	Completed
	Roof Slab	Completed	Completed	Completed	Completed
	Block Work	Work in progress	Work in progress	Completed	Completed
	Plastering -Internal		Work in progress	Completed	Completed
8	Second Floor				
	Column	Completed	Completed	Completed	Completed
	Roof Slab	Completed	Completed	Completed	Completed
	Block Work	Work in progress	Work in progress	Completed	Completed
	Plastering -Internal		Work in progress	Completed	Completed
9	Third Floor				
	Column	Completed	Completed	Completed	Completed
	Roof Slab	Work in progress	Completed	Completed	Completed
	Block Work	Work in progress	Work in progress	Completed	Completed
	Plastering -Internal		Work in progress	Completed	Completed
10	Fourth Floor				
	Column	Work in progress	Work in progress	Completed	Completed
	Roof Slab	Work in progress	Work in progress	Completed	Completed
	Block Work		Work in progress	Completed	Completed
	Plastering -Internal		Work in progress	Completed	Completed
11	Fifth Floor				
	Column	Work in progress	Work in progress	Completed	Completed
	Roof Slab	Work in progress	Work in progress	Completed	Completed
	Block Work		Work in progress	Completed	Completed
	Plastering -Internal			Completed	Completed
12	Above Terrace				
	Parapet		Work in progress	Completed	Completed
	OHT			Completed	Completed
	LMR			Completed	Completed
	SHR			Completed	Completed



Block-01 – Elevation View



Block-01 – Pour-1 –Third Floor Block work Lintel Shuttering & Concrete work in Progress



Block-01 – Pour-1 –Fifth Floor Slab Concrete work Completed



Block-01 – Pour-2 –Third Floor Slab Shuttering work in Progress



Block-02 – Elevation View



Block-02 – Pour-1 –Fourth Floor Plastering Work Nearing Completion



Block-02 – Pour-1 –Terrace Work Activities in Progress



Block-02 – Pour-1 – External East & North Side Plastering Work in Progress



Block-02 – Pour-2 –First Floor Block work Nearing Completion



Block-02 – Pour-2 –Second Floor Block Work in Progress



Block-02 – Pour-2 –Fourth Floor Slab Concrete Work Completed



Block-03 – Elevation View



Block-03 –Stilt Floor Column Beam Plastering Work in Progress



Block-03 –Third Floor Wall Putty Work in Progress



Block-03 –Fourth Floor Ceiling Putty Work in Progress



Block-03 – Toilet Plumbing Concealed & Suspended Pipeline Work Completed Up to 5th Floor



Block-03 – Terrace Parapet & Headroom Wall Plastering Work Completed



Block-03 –External Wall Texture Work in Progress



Block-04 – Elevation View



Block-01 –Stilt floor plastering work in Progress



Block-04 – Second floor toilet protective plastering Work in Progress



Block-04 – Fifth floor concealed pipeline work completed



Block-04 –Terrace floor Parapet wall Plastering Work in Progress



Block-04 – External Plastering Work in Progress

Thank
you!