

BEENA CLOVER


MONTHLY CONSTRUCTION UPDATES – FEBRUARY-26



Content

- ❖ Master Plan
- ❖ Structure –Progress Status & Photos
 - ✓ Shell & Core
 - ✓ Block Work
 - ✓ Plastering
- ❖ Finishing –Progress Status & Photos
 - ✓ Toilet Waterproofing
 - ✓ Tile Laying
 - ✓ Painting
 - ✓ MEP Work
 - ✓ Upvc Windows
 - ✓ Joinery
- ❖ External Development

MASTER PLAN



STRUCTURE -PROGRESS STATUS & PHOTOS

S.No	Activity	Block -01	Block -02	Block -03	Block -04
1	Excavation	Completed	Completed	Completed	Completed
2	Foundation	Completed	Completed	Completed	Completed
3	Plinth Beam	Completed	Completed	Completed	Completed
4	Back Filling	Completed	Completed	Completed	Completed
5	Stilt Floor -Column	Completed	Completed	Completed	Completed
6	Stilt Floor Roof Slab	Completed	Completed	Completed	Completed
7	First Floor				
	Column	Completed	Completed	Completed	Completed
	Roof Slab	Completed	Completed	Completed	Completed
	Block Work	Completed	Completed	Completed	Completed
	Plastering -Internal	Work in progress	Work in progress	Completed	Completed
8	Second Floor				
	Column	Completed	Completed	Completed	Completed
	Roof Slab	Completed	Completed	Completed	Completed
	Block Work	Work in progress	Completed	Completed	Completed
	Plastering -Internal	Work in progress	Work in progress	Completed	Completed
9	Third Floor				
	Column	Completed	Completed	Completed	Completed
	Roof Slab	Completed	Completed	Completed	Completed
	Block Work	Work in progress	Work in progress	Completed	Completed
	Plastering -Internal	Work in progress	Work in progress	Completed	Completed
10	Fourth Floor				
	Column	Completed	Completed	Completed	Completed
	Roof Slab	Work in progress	Completed	Completed	Completed
	Block Work	Work in progress	Work in progress	Completed	Completed
	Plastering -Internal		Work in progress	Completed	Completed
11	Fifth Floor				
	Column	Work in progress	Completed	Completed	Completed
	Roof Slab	Work in progress	Completed	Completed	Completed
	Block Work	Work in progress	Work in progress	Completed	Completed
	Plastering -Internal		Work in progress	Completed	Completed
12	Above Terrace				
	Parapet	Work in progress	Work in progress	Completed	Completed
	OHT			Completed	Completed
	LMR		Work in progress	Completed	Completed
	SHR			Completed	Completed



Block-01 – Elevation View



Block-01 – Pour-2 – Fourth Floor Roof Slab Shuttering work in Progress



Block-01 – Pour-2 – Second floor Block Work in Progress



Block-01 – Pour-1 – Fourth Floor Lintel Concrete work in Progress



Block-01 – Pour-2 – First Floor Plastering work in Progress



Block-01 – Pour-1 – Above Terrace work in Progress



Block-02 – Elevation View



Block-02 – Pour-2 – Above Terrace Work in Progress



Block-02 – Pour-2 –First Floor Plastering Nearing Completion



Block-02 – Pour-2 –Second Floor Plastering work in progress



Block-02 – Pour-2 – Third Floor Lintel Concrete work in progress



Block-02 – Pour-2 – Fourth Floor Block work in progress



Block-02 – Pour-1 – 1st ,2nd ,3rd and 4th Floor Toilet Waterproofing Nearing Completion



Block-02 – Pour-1 – Upto 5th floor POP Work Completed



Block-02 – Pour 1 North & West Outer Texture Work in Progress



Block-03 – Elevation View



Block-03 – Stilt Floor Ceiling & Column Putty work in progress



Block-03 – First Floor Flooring Tile Laying work in Progress



Block-03 – Second Floor Toilet Tile Laying work in Progress



Block-03 – Terrace Waterproofing work in Progress



Block-03 – Elevation Toilet Covering work in Progress



Block-04 – Elevation View



Block-04 – First Floor Ceiling & Wall Putty work in Progress



Block-04 – Second Floor Ceiling Putty work in Progress



Block-04 – Third Floor Ceiling Putty work in Progress



Block 4 Model Flat & Sales office Work in Progress



Block-04 – Lift Plastering Work in Progress



Block-04 – External Texture Work in Progress

Thank
you!