

BEENA CLOVER

MONTHLY CONSTRUCTION UPDATES – JANUARY-26



Content

- ❖ Master Plan
- ❖ Structure –Progress Status & Photos
 - ✓ Shell & Core
 - ✓ Block Work
 - ✓ Plastering
- ❖ Finishing –Progress Status & Photos
 - ✓ Toilet Waterproofing
 - ✓ Tile Laying
 - ✓ Painting
 - ✓ MEP Work
 - ✓ Upvc Windows
 - ✓ Joinery
- ❖ External Development

MASTER PLAN



STRUCTURE -PROGRESS STATUS & PHOTOS

S.No	Activity	Block -01	Block -02	Block -03	Block -04
1	Excavation	Completed	Completed	Completed	Completed
2	Foundation	Completed	Completed	Completed	Completed
3	Plinth Beam	Completed	Completed	Completed	Completed
4	Back Filling	Completed	Completed	Completed	Completed
5	Stilt Floor -Column	Completed	Completed	Completed	Completed
6	Stilt Floor Roof Slab	Completed	Completed	Completed	Completed
7	First Floor				
	Column	Completed	Completed	Completed	Completed
	Roof Slab	Completed	Completed	Completed	Completed
	Block Work	Work in progress	Completed	Completed	Completed
	Plastering -Internal	Work in progress	Work in progress	Completed	Completed
8	Second Floor				
	Column	Completed	Completed	Completed	Completed
	Roof Slab	Completed	Completed	Completed	Completed
	Block Work	Work in progress	Work in progress	Completed	Completed
	Plastering -Internal	Work in progress	Work in progress	Completed	Completed
9	Third Floor				
	Column	Completed	Completed	Completed	Completed
	Roof Slab	Completed	Completed	Completed	Completed
	Block Work	Work in progress	Work in progress	Completed	Completed
	Plastering -Internal	Work in progress	Work in progress	Completed	Completed
10	Fourth Floor				
	Column	Work in progress	Work in progress	Completed	Completed
	Roof Slab	Work in progress	Work in progress	Completed	Completed
	Block Work	Work in progress	Work in progress	Completed	Completed
	Plastering -Internal		Work in progress	Completed	Completed
11	Fifth Floor				
	Column	Work in progress	Work in progress	Completed	Completed
	Roof Slab	Work in progress	Work in progress	Completed	Completed
	Block Work		Work in progress	Completed	Completed
	Plastering -Internal		Work in progress	Completed	Completed
12	Above Terrace				
	Parapet	Work in progress	Work in progress	Completed	Completed
	OHT			Completed	Completed
	LMR			Completed	Completed
	SHR			Completed	Completed



Block-01 – Elevation View



Block-01 – Pour-1 –Fourth Floor Block work in Progress



Block-01 – Pour-1 –Second Floor Plastering work in Progress



Block-01 – Pour-1 – Terrace floor Block Work in Progress



Block-01 – Pour-2 –Fourth Floor Slab Shuttering work in Progress



Block-02 – Elevation View



Block-02 – Pour-2 –First Floor Plastering Work in Progress



Block-02 – North & West Outer Plastering Work in Progress



Block-02 – Pour-2 –Second Floor Block work in progress



Block-02 – Pour-2 – Fifth Floor Column Concrete Work in Progress



Block-03 – Elevation View



Block-03 – Stilt Floor Ceiling & Column Putty work in progress



Block-03 – Fifth floor wall putty work in Progress



Block-03 – West Side Outer Texture work in Progress



Block-04 – Elevation View



Block-01 –Stilt floor plastering work in Progress



Block-01 –First Floor Model Flat Tile Laying Work in Progress



Block-04 –Fifth Floor protective plastering Work in Progress



Block-04 –Third floor concealed ledge Blockwork in Progress



Block-04 –Terrace floor Headroom wall Plastering Work Completed



Block-04 – External Texture Work in Progress

*Thank
you!*