



SNo.	Work Description	% Of Completion
Internal flat - Tile work & Kitchen Counter Slab Granite		
1	9th floor - Ledge wall & Threshold and Kitchen counter slab Granite work in Progress	40%
2	10th floor - Ledge wall & Threshold and Kitchen counter slab Granite work in Progress	60%
Internal Flat Plumbing Water Line & Sunken Soil, Waste Line and Common Plumbing Work		
3	8th floor Ceiling Suspended Plumbing line work in progress	60%
4	8th to 12th floor Plumbing shaft branch line conection work Completed	95%
Internal Flat Wiring Work		
5	12th floor Corridor Wiring work completed	95%
6	11th floor Corridor Wiring work completed	95%
7	10th floor Corridor Wiring work completed	95%
8	9th floor Corridor Wiring work in Progress	60%
9	8th floor Corridor Wiring work in Progress	40%
8	8th floor Wiring & Switch plate and DB Dressing work Completed	95%
Internal Flat - Gypsum False ceiling Work		
9	12th floor False ceiling work Completed	95%
10	11th floor False ceiling work Completed	95%
11	10th floor False ceiling work Completed	95%
12	9th floor False ceiling Channel work in progress	45%
13	8th floor False ceiling Channel work Completed	95%
Internal Flat - Wall & Ceiling Putty Work		
14	12th floor Internal flat Wall & Ceiling 1st Coat Painting work Completed	95%
15	11th floor Internal flat Wall & Ceiling 1st Coat Painting work Completed	95%
16	10th floor Internal flat Wall & Ceiling 1st Coat Painting work Completed	95%
17	9th floor Internal flat Wall Primer work in progress	25%
18	8th floor Internal flat Wall & Ceiling 1st Coat Painting work Completed	95%
19	12th floor Corridor 2nd Coat Putty work completed	95%
20	11th floor Corridor 2nd Coat Putty work completed	95%
21	10th floor Corridor 2nd Coat Putty work completed	95%
22	9th floor Corridor 2nd Coat Putty work completed	95%
23	8th floor Corridor 2nd Coat Putty work in Progress	25%

SNo.	Work Description	% Of Completion
Internal flat Door Installation work		
24	8th floor Main door & Toilet door Installation work Completed	25%
25	11th floor Main door & Toilet door Installation work in Progress	50%
26	12th floor Main door & Toilet door Installation work Completed	95%
Common area work		
27	Entrance Canopy Glass fixing work Completed	95%
28	Entrance ACP Sheet fixing work Completed	95%
29	4th floor Private Terrace - Waterproofing Coating work in progress	45%
30	8th to 12th floor Internal flat Electrical shaft DB fixing work Completed	95%
31	HNS Pump Erection and Comissioning work Completed	95%
30	Lift No.2 Machine Erection work Completed	95%



Site Front View

Stilt Floor Driver Toilet Wall & Floor Tiles Laying work Completed



9th & 10th Suite Room Toilet Wall & Floor Tiles work Completed



8th to 12th floor 3 Nos of shaft plumbing water line branch valve fixing work completed



STP Revamping and Exhaust fan fixing work completed



HNS Pump Commissioning work Completed



Stilt floor to 7th floor Common area Communication Shaft Aluminum Louver door installation work Completed



12th floor Corridor Wiring work completed and 11th floor Corridor Wiring work in progress



8th to 12th floor - Suite room Electrical Wall chasing and box fixing work Completed



4th floor private terrace Waterproofing Coating work in progress



12th & 11th floor Ceiling & Wall 1st Coat Painting Work Completed 10th floor work in progress



12th & 11th floor Toilet and Kitchen area Ceiling
Grid false Ceiling work Completed



10th floor Toilet and Kitchen Ceiling Grid False
Ceiling work in Progress



8th floor Main & Toilet Door Installation work
Completed 12th floor work in progress



External CCTV Camera line and camera fixing
work completed



Thank you!