



DRA COVE

Monthly Construction Updates – June 2026

SNo.	Work Description	% Of Completion
Internal flat - Tile work & Kitchen Counter Slab Granite & Acid wash		
1	8th to 12th floor - Ledge Wall & Threshold and Kitchen counter slab Granite work Completed	100%
2	8th to 12th floor - Flooring & Toilet Wall & Floor Tiles work Completed	100%
3	Driveway Toilet - Flooring & Toilet Wall & Floor Tiles work Completed	100%
4	11th & 12th floor - Flooring & Toilet Tiles Acid Wash work Completed	100%
5	8th & 10th floor - Flooring POP Removing work Completed	100%
Corridor & Internal Flat Wiring Work		
1	8th to 12th floor - Corridor Wiring work completed	100%
2	8th, 9th 10th & 11th floor - Suite Room Wiring work Completed	100%
3	12th floor - Suite Room Wiring work in Progress	50%
4	12th floor - Corridor Grid Light fixing work Completed	100%
5	10th, 11th & 12th floor - Internal flat Testing work Completed	100%
Corridor & Internal Flat - Gypsum & Grid False ceiling Work		
1	8th to 12th floor - false Ceiling & Grid false Ceiling work Completed	100%
2	10th, 11th & 12th floor - Corridor Grid False ceiling work Completed	100%
3	8th & 9th floor - Corridor Grid False ceiling work in Progress	40%

SNo.	Work Description	% Of Completion
Internal Flat - Wall & Ceiling Putty Work		
1	8th, 10th, 11th & 12th floor Internal flat Wall & Ceiling 1st Coat Painting work Completed	100%
2	9th floor Internal flat Wall & Ceiling 1st Coat Painting work in Progress	100%
Corridor & Internal flat Door Installation work		
1	8th to 12th floor Main door & Toilet door Installation work Completed	100%
2	8th to 12th floor - Suite Room Main & Toilet door Installation work Completed	100%
3	801 flat - Main & Toilet door Installation work in Progress	10%
4	8th to 12th floor - Corridor Grabage room Door Installation work in Progress	25%
Common area work		
1	External Vertical Plumbing Pipe Line Laying work Completed	95%
2	Stilt Plumbing Pipe Line Chamber conection work in Progress	50%
3	Plumbing Shaft Vertical Plumbing Pipe Line Laying work Completed	95%
4	4th floor Private Terrace - Waterproofing & Screed Concreate work Completed	95%
5	4th floor Private Terrace - Weathering Tile Laying work in Progress	25%
6	Stilt, 1st to 4th floor Shaft Aluminium Louver door Installation work Completed	95%
7	5th & 6th floor Shaft Aluminium Louver door Installation work in Progress	25%
8	804 flat - Interior work Completed	95%



Site Front View

8th Floor to 12th Floor Internal Door Fixing Work Completed



8th Floor to 12th Floor Corridor flooring Tiles Laying work Completed



8th to 12th Floor Suite Room Wiring work in Progress



8th to 12th Floor Internal Flat False ceiling work completed (Except Suite Room)



12th Floor Corridor False Ceiling work in Progress



8th to 12th Floor Suite Room Threshold & Ledge wall Top Granite laying work Completed



Plumbing Shaft 8th to 4th floor Vertical and Suspended Pipe line laying work Completed



External Vertical Waste & Soil Line Plumbing Pipe Laying work Completed



8th to 12th Floor Suite Room Glass Cleaning Work Completed



12th & 11th floor Ceiling & Wall 1st Coat Painting Work Completed 10th floor work in progress



**12th & 11th floor Toilet and Kitchen area Ceiling
Grid false Ceiling work Completed**



**10th floor Toilet and Kitchen Ceiling Grid False
Ceiling work in Progress**



Flat No. 804 Flat Mockup Interior work Completed



12th, 11th & 10th Floor Internal Flat Acid Wash Cleaning work Completed



Flat No. 804 Flat Mockup Interior work Completed



12th, 11th & 10th Floor Internal Flat Acid Wash Cleaning work Completed



Thank you!