



| SNo.                                                                 | Work Description                                                                           | % Of Completion |
|----------------------------------------------------------------------|--------------------------------------------------------------------------------------------|-----------------|
| Internal flat - Tile work & Kitchen Counter Slab Granite & Acid wash |                                                                                            |                 |
| 1                                                                    | 8th to 12th floor - Ledge Wall & Threshold and Kitchen counter slab Granite work Completed | 100%            |
| 2                                                                    | 8th to 12th floor - Flooring & Toilet Wall & Floor Tiles work Completed                    | 100%            |
| 3                                                                    | Driveway Toilet - Flooring & Toilet Wall & Floor Tiles work Completed                      | 100%            |
| 4                                                                    | 11th & 12th floor - Flooring & Toilet Tiles Acid Wash work Completed                       | 100%            |
| 5                                                                    | 8th & 10th floor - Flooring POP Removing and Acid wash Cleaning work Completed             | 100%            |
| 6                                                                    | 12 floor Internal flat - Deep Cleaning work in Progress                                    | 40%             |
| Corridor & Internal Flat Wiring Work                                 |                                                                                            |                 |
| 1                                                                    | 8th to 12th floor - Corridor Wiring work completed                                         | 100%            |
| 2                                                                    | 8th to 12th floor - Suite Room Wiring work Completed                                       | 100%            |
| 3                                                                    | 8th to 12th floor - Corridor Grid Light fixing work Completed                              | 100%            |
| 4                                                                    | 10th, 11th & 12th floor - Internal flat Testing work Completed                             | 100%            |
| Corridor & Internal Flat - Gypsum & Grid False ceiling Work          |                                                                                            |                 |
| 1                                                                    | 8th to 12th floor - False Ceiling & Grid false Ceiling work Completed                      | 100%            |
| 2                                                                    | 8th to 12th floor - Corridor Grid False ceiling work Completed                             | 100%            |
| 3                                                                    | 8th to 12th floor Suite Room - Gypsum and Toilet Grid False ceiling work Completed         | 100%            |

| SNo.                                            | Work Description                                                                  | % Of Completion |
|-------------------------------------------------|-----------------------------------------------------------------------------------|-----------------|
| Internal Flat - Wall & Ceiling Putty Work       |                                                                                   |                 |
| 1                                               | 8th to 12th floor Internal flat Wall & Ceiling Final Coat Painting work Completed | 100%            |
| 2                                               | 8th to 12th floor - Suite Room 1st Coat Painting work in Progress                 | 50%             |
| 3                                               | 8th to 12th floor - Corridor 1st Coat Painting work Completed                     | 100%            |
| Corridor & Internal flat Door Installation work |                                                                                   |                 |
| 1                                               | 8th to 12th floor Main door & Toilet door Installation work Completed             | 100%            |
| 2                                               | 8th to 12th floor - Suite Room Main & Toilet door Installation work Completed     | 100%            |
| 3                                               | 801 flat - Main & Toilet door Installation work in Progress                       | 10%             |
| 4                                               | 8th to 12th floor - Corridor Grabage room Door Installation work Completed        | 100%            |
| 5                                               | 9th to 12th floor - Suite Room CP Sanitary Fittings Testing work Completed        | 100%            |
| Common area work                                |                                                                                   |                 |
| 1                                               | External Vertical Plumbing Pipe Line Laying work Completed                        | 100%            |
| 2                                               | Stilt Plumbing Pipe Line Chamber conection work Completed                         | 100%            |
| 3                                               | Plumbing Shaft Vertical Plumbing Pipe Line Laying work Completed                  | 100%            |
| 4                                               | 4th floor Private Terrace - Waterproofing & Screed Concreate work Completed       | 100%            |
| 5                                               | 4th floor Private Terrace - Weathering Tile Laying work Completed                 | 100%            |
| 6                                               | Stilt, 1st to 7th floor Shaft Aluminium Louver door Installation work Completed   | 100%            |
| 7                                               | 804 flat - Interior work Completed                                                | 100%            |
| 8                                               | Suite Room AC Copper and Drain Pipe line laying work in progress                  | 50%             |
| 9                                               | Lift No.1 & 2 Handing Over Process work in progress                               | 80%             |



**Site Front View**

**8<sup>th</sup> to 12<sup>th</sup> Floor Garbage Room Door & Shaft Door  
Painting work Completed**



**4<sup>th</sup> Floor Private Terrace Waterproofing &  
Weathering flooring Tile Laying Work Completed**



**9<sup>th</sup> to 12<sup>th</sup> Floor Internal Flat Toilet CP Sanitary  
Fittings Fixing Work Completed Testing work in  
Progress**



**8<sup>th</sup> Floor Internal Flat Final Coat Painting work  
Completed**



**8<sup>th</sup> to 12<sup>th</sup> Floor Suite Room 2<sup>nd</sup> coat putty work  
Completed**



**8<sup>th</sup> to 12<sup>th</sup> Floor Lift Lobby Entrance Threshold  
Granite fixing work Completed**



## 8<sup>th</sup> to 12<sup>th</sup> Floor Internal flat 2<sup>nd</sup> Coat Painting work Completed



## 8<sup>th</sup> to 12<sup>th</sup> Floor Suite Room Acid Wash cleaning Work Completed



### Lift Lobby Marble Polish – 4<sup>th</sup> Floor to 7<sup>th</sup> Floor Completed



### Common area Communication Shaft flooring Tile Laying Work Completed



**8<sup>th</sup> to 12<sup>th</sup> Floor Corridor Wall 1<sup>st</sup> Coat  
Painting work completed**



**9<sup>th</sup> to 12<sup>th</sup> Floor Corridor False Ceiling Light  
fixing Work Completed**



*Thank you!*