



DRA COVE

Monthly Construction Updates – March 2026

| SNo. | Work Description | % Of Completion |
|-------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------|-----------------|
| Internal flat - Tile work | | |
| 1 | 8th floor - Flooring Tiles Laying Completed | 95% |
| 2 | 8th floor - Toilet Wall & Floor Tiles Laying Completed | 95% |
| 3 | 10th floor - Flooring Tiles Laying Completed | 95% |
| 4 | 10th floor - Toilet Wall & Floor Tiles Laying Completed | 95% |
| 5 | 11th floor - Flooring Tiles Laying Completed | 95% |
| 6 | 11th floor - Toilet Wall & Floor Tiles Laying Completed | 95% |
| 6 | 12th floor - Flooring Tiles Laying Completed | 95% |
| 7 | 12th floor - Toilet Wall & Floor Tiles Laying Completed | 95% |
| Toilet Sunken Waterproofing & Filling Work | | |
| 8 | 8th, 10th, 11th & 12th floor Toilet Sunken Waterproofing & Filling work Completed | 95% |
| 9 | 9th floor & Suite Room Toilet Filling work in Progress | 10% |
| Internal Flat Plumbing Water Line & Sunken Soil, Waste Line and Common Plumbing Work | | |
| 10 | 8th, 9th, 10th, 11th, 12th & Suite Room Toilet Water Line & Soil Waste Line Plumbing Pipe work Completed | 95% |
| 11 | 8th, 10th, 11th & 12th floor Toilet Flush Tank and Ledge Wall work completed | 95% |
| 12 | 9th floor & Suite Room Flush Tank and Ledge Wall work in Progress | 45% |
| 13 | STP Treated Water Plumbing Line work Completed | 95% |
| 14 | STP Treated Water Plumbing Line Pump Erection work Completed | 95% |
| 14 | HNS Pump Suspended Plumbing Line work Completed | 85% |
| 15 | HNS Pump Erection work Completed | 85% |

| SNo. | Work Description | % Of Completion |
|-------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------|-----------------|
| Internal Flat Window Grill Fixing and Kitchen MS 'L' Angle fixing Work | | |
| 16 | 12th floor Window Grill Fixing work Completed | 95% |
| 17 | 11th floor Window Grill Fixing work Completed | 95% |
| 18 | 10th floor Window Grill Fixing work Completed | 65% |
| 19 | 8th, 9th, 10th, 11th, 12th & Suite Room Kitchen Counter MS 'L' Angle fixing work Completed | 95% |
| Internal Flat Wiring Work | | |
| 20 | 12th floor Wiring work in progress | 25% |
| Internal Flat Painting Work | | |
| 21 | 12th floor Primer work Completed | 95% |
| 22 | 11th floor Primer work Completed | 95% |
| 23 | 12th floor 1st coat Painting work in progress | 25% |
| 24 | 10th floor 2nd Coat Putty work Completed | 95% |
| 25 | 8th & 9th floor 2nd Coat Putty work in progress | 45% |
| Lift No.1 & 2 Erection work | | |
| 26 | Lift No.1 - Erection and Commissioning work Completed | 95% |
| 27 | Lift No.2 - Railing Erection work in Progress | 40% |
| STP Erection and Commissioning work | | |
| 28 | STP Plant - Erection and Commissioning work Completed | 95% |
| EB Pannel Meter fixing work | | |
| Common area work | | |
| 29 | Entrance Canopy Template work in progress | 45% |
| 30 | 4th floor Private Terrace - Waterproofing Floor Chipping work in progress | 75% |
| 31 | 4th floor Private - Terrace Damaged Glass Rectification work Completed | 95% |



Site Front View

**9th floor toilet sunken water testing
Work Completed**



**4th floor Private Terrace Rain Water
Leakage Waterproofing - Floor Chipping
work in progress**



HNS Pump installation work completed



8th to 12th floor suit room Flush Tank fixing work Completed



**9th floor Toilet Sunken Waste & Soil Plumbing
Line work Completed**



**STP Treated Water Plumbing Pipe
line work Completed**



10th floor Kitchen counter top L angle fixing work completed



Suit Room and 9th floor Kitchen counter top 'L' angle fixing work completed



10th floor 2nd coat putty work Completed



12th floor Primer work Completed



11th floor Primer work Completed



**8th to 12th floor suit room vertical
ACP sheet work completed**



10th floor Internal flooring Tiles Laying work Completed



9th floor 1st coat putty work in Progress



**4th floor Private Terrace Toughened Glass
Fixing work Completed**



**Entrance Lobby Canopy Template
plywood cutting fixing work in
progress**



Thank you!