



D'ELITE

CONSTRUCTION UPDATE PHOTOS JULY 2024



South-East Elevation



West side Elevation



North side Elevation



External 2nd Coat Painting Work Completed,



Internal Flats 2nd Coat Painting Up to 10th Floor Completed , 11th Floor Work In Progress



Internal Flat Acid Wash Work Up to 9th Floor Completed



OSR Landscape Work In Progress



1st Floor Amenities Hardscape Work in progress



1st & 10th Floor Amenities Glass Door Fixing Work Completed



10th Floor Level Low Terrace Hardscape Work In Progress



10th Floor Low Terrace OTS Covering Work completed



Basement 2nd Coat painting Work Completed



Electrical Room-1&2 Termination Work In Progress ,



Common Area CCTV Camera Fixing Work In Progress



Networking Cable Pulling And Splicing Work Completed



Stilt Floor Lift Lobby False Ceiling Work Completed



Lift -2 & 3 Erection Work In Progress ,




**Stilt Floor Podium Chips Filling Work completed , Paver Laying
Work In Progress**



WTP Pump Room Tile Flooring Work Completed



Fire Shaft Doors Fixing Work Completed, Fire pipe 2nd coat painting work in progress



**Basement Car Park Marking , Column Guard Fixing And Ramp
Center median Fixing Work Completed**



Transformer Erection Work Completed



1st Floor GYM & MPH False Ceiling Work Completed



*Thank
you!*