#### DRA D'ELITE THE ELITE LIFESTYLE



## D'ELITE CONSTRUCTION UPDATE PHOTOS JULY 2024





STAGE COMPLETION STATUS UP TO JULY'24			
S. No	Description	Status	Remarks
1	Completion of Foundation	Completed.	
2	Completion of Stilt Floor Roof	Completed.	
3	Completion of First Floor Roof	Completed.	
4	Completion of Third Floor Roof	Completed.	
5	Completion of Fifth Floor Roof	Completed.	
6	Completion of Seventh Floor Roof	Completed.	
7	Completion of Nineth Floor Roof	Completed.	
8	Completion of Eleventh Floor Roof	Completed.	
9	Completion of Masonry Work	Completed.	
10	Completion of Internal Plastering	Completed.	
12	Completion of Internal Finishes	Tiling snag & painting work in progress	







### **South-East Elevation**







#### West side Elevation







#### North side Elevation








## External 2<sup>nd</sup> Coat Painting Work Completed,










#### Internal Flats 2<sup>nd</sup> Coat Painting Up to 10<sup>th</sup> Floor Completed, 11<sup>th</sup> Floor Work In Progress







### Internal Flat Acid Wash Work Up to 9<sup>th</sup> Floor Completed







#### **OSR Landscape Work In Progress**








#### 1<sup>st</sup> Floor Amenities Hardscape Work in progress







## 1<sup>st</sup> & 10<sup>th</sup> Floor Amenities Glass Door Fixing Work Completed







## 10<sup>th</sup> Floor Levell Low Terrace Hardscape Work In Progress








# **10<sup>th</sup> Floor Low Terrace OTS Covering Work completed**








## **Basement 2<sup>nd</sup> Coat painting Work Completed**










## **Electrical Room-1&2 Termination Work In Progress**,







#### **Common Area CCTV Camera Fixing Work In Progress**









#### Networking Cable Pulling And Splicing Work Completed







## **Stilt Floor Lift Lobby False Ceiling Work Completed**








#### Lift -2 & 3 Erection Work In Progress,







#### Stilt Floor Podium Chips Filling Work completed , Paver Laying Work In Progress








#### WTP Pump Room Tile Flooring Work Completed








Fire Shaft Doors Fixing Work Completed, Fire pipe 2<sup>nd</sup> coat painting work in progress







**Basement Car Park Marking**, Column Guard Fixing And Ramp **Center median Fixing Work Completed** 







#### **Transformer Erection Work Completed**









## 1<sup>st</sup> Floor GYM & MPH False Ceiling Work Completed





