



DRA HARMONY
CONSTRUCTION UPDATES – AUGUST 2024

STAGE COMPLETION STATUS UP TO JULY 24

S. No	Description	Status	Remarks
1	Completion of Foundation	Completed	
2	Completion of Stilt Floor Roof	Completed	
3	Completion of Upper Stilt Floor Roof	Completed	
4	Completion of First Floor Roof	Completed	
5	Completion of Third Floor Roof	Completed	
6	Completion of Fifth Floor Roof	Completed	
7	Completion of Seventh Floor Roof	Completed	
8	Completion of Nineth Floor Roof		
9	Completion of Eleventh Floor Roof		
10	Completion of Thirteenth Floor Roof		
11	Completion of Masonry Work		
12	Completion of Internal Plastering		
13	Completion of Internal Finishes		



Main Building – Eighth Floor Slab Concrete Work Completed.



Main Building – Eighth Floor Column Starter & Reinforcement Work In Progress.



Main Building – Sixth Floor Hacking & Surface Grinding Work In Progress.



Main Building – Fourth Floor Block Work Completed.



Main Building –Fifth Floor Block Work In progress.



Main Building – Sixth Floor Block Work In Progress.



Main Building – First Floor Kitchen Counter Slab Work In Progress.



Main Building – Fourth Floor Button Marking Work In Progress.



Main Building Electrical – Second Floor Wall Chasing Work In Progress.



Main Building Plumbing – Third Floor AC Sleeve Fixing Work In Progress.



STP – Head Room Column Concrete Work Completed.



External Compound Wall Plastering – East side Plastering Work In Progress.



Storm Water Trench – North Side Trench Raft concrete work Completed & Wall Concrete Work In Progress.



Main Building – West & North Side View.



Main Building –East Side View.



Main Building –West Side View.



Main Building - South Side View.



Main Building - North Side View

*Thank
you!*