



DRA HARMONY
CONSTRUCTION UPDATES – NOVEMBER-2025

STAGE COMPLETION STATUS UP TO NOVEMBER-25

S. No	Description	Status	Remarks
1	Completion of Foundation	Completed	
2	Completion of Stilt Floor Roof	Completed	
3	Completion of Upper Stilt Floor Roof	Completed	
4	Completion of First Floor Roof	Completed	
5	Completion of Third Floor Roof	Completed	
6	Completion of Fifth Floor Roof	Completed	
7	Completion of Seventh Floor Roof	Completed	
8	Completion of Ninth Floor Roof	Completed	
9	Completion of Eleventh Floor Roof	Completed	
10	Completion of Thirteenth Floor Roof	Completed	
11	Completion of Masonry Work	Completed	
12	Completion of Internal Plastering	Completed	
13	Completion of Internal Finishes	In Progress	

PROGRESS PHOTOS

WEST ELEVATION - PREVIOUS MONTH



WEST ELEVATION - THIS MONTH



PROGRESS PHOTOS

EAST ELEVATION – PREVIOUS WEEK



EAST ELEVATION – THIS WEEK



PROGRESS PHOTOS

SOUTH ELEVATION - PREVIOUS WEEK



SOUTH ELEVATION - THIS WEEK



PROGRESS PHOTOS

NORTH ELEVATION - PREVIOUS MONTH



NORTH ELEVATION - THIS MONTH



PROGRESS PHOTOS



9th FLOOR DOOR FIXING WORK IN PROGRESS



UPVC 11th FLOOR FIXING Work IN PROGRESS

PROGRESS PHOTOS



6TH FLOOR GRILL FIXING WORK COMPLETED



2ND FLOOR SOAP WASH WORK IN PROGRESS

PROGRESS PHOTOS



LIFT CORRIDOR GRANITE WORK IN PROGRESS



LIFT GRANITE WORK IN PROGRESS

PROGRESS PHOTOS



7TH FLOOR WIRING WORK COMPLETED



STILT & UPPER STILT TRAY FIXING WORK IN PROGRESS

PROGRESS PHOTOS



OTS – PRESS TILES LAYING WORK COMPLETED



COMMON TERRACE – PRESS TILES LAYING COMPLETED

PROGRESS PHOTOS



EXTERNAL – SOUTHSIDE 1ST COAT PAINTING WORK IN PROGRESS



OTS&SHAFT – 1ST COAT PAINTING IN PROGRESS

PROGRESS PHOTOS




PARAPET TEXTURE WORK IN PROGRESS



ENTRANCE ARCH 1ST COAT PAINTING WORK IN PROGRESS



AMENITY BLOCK TEXTURE WORK COMPLETED



10TH FLOOR 1ST PAINTING WORK COMPLETED

PROGRESS PHOTOS



FIRE FIGHTING - STILT FLOOR WORK IN PROGRESS



PLUMBING - UPPER STILT RING MAIN LINE WORK IN PROGRESS

PROGRESS PHOTOS



**UPPER STILT 1ST PART SCREED CONCRETE WORK
COMPLETED**



UPPER STILT SCREED CURING WORK IN PROGRESS

PROGRESS PHOTOS



BADMINTON COURT- FILLING WORK IN PROGRESS



PLUMBING CHAMBER – EXCAVATION WORK IN PROGRESS

PROGRESS PHOTOS



EXTERNAL – ELECTRICAL CHAMBER WORK IN PROGRESS



**EXTERNAL – SOUTH&EAST SIDE TRENCH PRECAST SLAB
LAYING COMPLETED**



**EXTERNAL – COMPOUNDWALL HYDRANT LINE FIXING
WORK IN PROGRESS**



EXTERNAL - TRANSFORMER YARD WORK IN PROGRESS

THANKS