



DRA HARMONY

CONSTRUCTION UPDATES – OCTOBER-2025



West side Elevation



East Side Elevation



South Side Elevation



North Side Elevation



Stilt Floor Plastering – Block Work & Plastering Work In Progress



Amenity Block External Plastering – South Side Work In Progress



Compound Wall Plastering – West Side Work In Progress



Corridor Tiles – Up to 13th Floor Completed



Putty Work – 11th Floor Work In Progress



Tenth Floor – Primer Work In Progress



OTS & Shaft - Painting Work In Progress



External Painting – 1st Coat Work In Progress



External Texture – North Side Work In Progress



Amenity Block – Brickbat Work Completed



Terrace – Press Tiles Laying Grouting Work Completed



Private Terrace – Waterproofing Work In Progress



Plumbing – Vertical Line Work In Progress



Plumbing – Upper Stilt Ring Main Line Work In Progress



EB Panel room – Primer Work In Progress



DG Bed Work Completed



UPVC Window – Fixing Work In Progress



Balcony Glass Handrail – Fixing Work In Progress



Lift – Frame Fixing Work In Progress



Balcony Trap Door – Fixing Work In Progress



Window Grill – Fixing Work In Progress



Staircase Handrail – West Side Fixing Work In Progress



Aluminum Louver – Elevation Fixing Work In Progress



OTS Covering – Fabrication Work In Progress



Electrical- 3rd Floor Wiring & DB Termination Work In Progress



Entrance- Landscape Wall Block Work Completed



Entrance Compound wall – Plinth Beam Work In Progress



Trench – Precast Slab Laying Work In Progress



Upper Stilt – Fire Fighting Work In Progress



Terrace – Hydrant Line Work In Progress

*Thank
you!*