





DRA HARMONY
CONSTRUCTION UPDATES – FEBRUARY 2025





Over all percentage of Completion

S. No	Project Code	Project Name	Saleable Area in Sqft	Cumulative% Achieved up to Feb-25	Status
1	DRA-19	Harmony	1,88,014	70%	Structure & Finishing Ongoing





STAGE COMPLETION STATUS UP TO FEB -25							
S. No	Description	Status	% of Completion	Remarks			
1	Completion of Foundation	Completed	100%				
2	Completion of Stilt Floor Roof	Completed	100%				
3	Completion of Upper Stilt Floor Roof	Completed	100%				
4	Completion of First Floor Roof	Completed	100%				
5	Completion of Third Floor Roof	Completed	100%				
6	Completion of Fifth Floor Roof	Completed	100%				
7	Completion of Seventh Floor Roof	Completed	100%				
8	Completion of Ninth Floor Roof	Completed	100%				
9	Completion of Eleventh Floor Roof	Completed	100%				
10	Completion of Thirteenth Floor Roof						
11	Completion of Masonry Work	Upto 11 th Floor Completed	80%				
12	Completion of Internal Plastering	Upto 8 th Floor Completed	55%				
13	Completion of Internal Finishes	Work In Progress					





DRA HOME OF PRIDE

West side Elevation







East Side Elevation








HOME OF PRIDE

South Side Elevation








North Side Elevation







Twelfth Floor Roof Slab Concrete Work Completed










Eleventh Floor Block Work Completed







Tenth Floor Kitchen Counter Slab Work In Progress









Eighth Floor Plastering Work Completed









Electrical – Tenth Floor Wall Chasing Work In Progress










Plumbing – Ninth Floor Core Cutting Work Completed









Plumbing – Seventh Floor Suspended Line Work In Progress









Waterproofing – Sixth & Seventh Floor Waterproofing Work In Progress









Fourth & Fifth Floor 1st Coat Wall Putty Work Completed


















Third & Fourth Floor Wall Tile Laying Work In Progress









First & Second Floor Tile Laying Work In Progress







Entrance Structure – Column Concrete Work Completed & Roof Slab Work In Progress







External – Type-1 Compound wall Block Work In Progress





Thank you!