



# **DRA HARMONY**

## **CONSTRUCTION UPDATES – AUGUST-2025**

**STAGE COMPLETION STATUS UP TO AUGUST-25**

<b>S. No</b>	<b>Description</b>	<b>Status</b>	<b>Remarks</b>
1	Completion of Foundation	Completed	
2	Completion of Stilt Floor Roof	Completed	
3	Completion of Upper Stilt Floor Roof	Completed	
4	Completion of First Floor Roof	Completed	
5	Completion of Third Floor Roof	Completed	
6	Completion of Fifth Floor Roof	Completed	
7	Completion of Seventh Floor Roof	Completed	
8	Completion of Ninth Floor Roof	Completed	
9	Completion of Eleventh Floor Roof	Completed	
10	Completion of Thirteenth Floor Roof	Completed	
11	Completion of Masonry Work	Completed	
12	Completion of Internal Plastering	Completed	
13	Completion of Internal Finishes	In Progress	





**West side Elevation**



**East Side Elevation**





**South Side Elevation**





**North Side Elevation**





**Terrace – Brick Bat Coba Work In Progress**



**Upper Stilt -Plastering Work In Progress**





**Staircase Plastering Work Completed**



**Staircase Tiles Work In Progress**





**Eleventh Floor - Flooring Tiles Work In Progress**



**Twelfth Floor – Wall Tiles Work Completed**





**Eighth Floor – 2<sup>nd</sup> Coat Wall Putty Work In Progress**



**Seventh Floor – Primer Work In Progress**





**First Coat Painting – 1<sup>st</sup> and 2<sup>nd</sup> Floor Completed**



**First Coat Painting – 3<sup>rd</sup> and 4<sup>th</sup> Floor Work In Progress**





**External Texture – South Side Work In Progress**






**External Texture – South Side Primer Work Completed**





**OTS & Shaft – Primer Work In Progress**



**External Plastering – South Side Final Coat Work In Progress**





**Ramp Plastering – Exit Ramp Work In Progress**



**Amenity Block Plastering – Internal & Parapet Work In Progress**





**Compound wall Plastering – North Side Work In Progress**



**OTS & Shaft Plastering Work In Progress**





**Storm Water Trench – North & West Side Work In Progress**





**AC Ledge Fixing Work In Progress**





**UPVC – Installation Work In Progress**



**False Ceiling – 2<sup>nd</sup> & 3<sup>rd</sup> Floor Work In Progress**





**Stilt Floor – PCC Cutting Work In Progress**





**Stilt Floor – Chamber Area PCC Filling Work In Progress**





**Plumbing – Stilt Floor Chamber Work In Progress**





**Plumbing – External Vertical Shaft Pipeline Work In Progress**





**Electrical – Amenity Block Electrical wall chasing Completed**



**Electrical – Lift Conduit Line Completed**



*Thank  
you!*