






DRA HARMONY
CONSTRUCTION UPDATES – JULY-2025



STAGE COMPLETION STATUS UP TO JULY-25			
S. No	Description	Status	Remarks
1	Completion of Foundation	Completed	
2	Completion of Stilt Floor Roof	Completed	
3	Completion of Upper Stilt Floor Roof	Completed	
4	Completion of First Floor Roof	Completed	
5	Completion of Third Floor Roof	Completed	
6	Completion of Fifth Floor Roof	Completed	
7	Completion of Seventh Floor Roof	Completed	
8	Completion of Ninth Floor Roof	Completed	
9	Completion of Eleventh Floor Roof	Completed	
10	Completion of Thirteenth Floor Roof	Completed	
11	Completion of Masonry Work	Completed	
12	Completion of Internal Plastering	Completed	
13	Completion of Internal Finishes	In Progress	









West side Elevation















South Side Elevation







North Side Elevation









Terrace Waterproofing – Final Bonding Test Work In Progress









Upper Stilt-Plastering Work In Progress









Staircase Plastering Work In Progress










Staircase Tiles Work In Progress









Eleventh Floor - Flooring Tiles Work In Progress










Eleventh Floor – Wall Tiles Work Completed















AC Ledge Fixing Work In Progress









Plumbing – Stilt Floor Chamber Brick Work In Progress







Plumbing – External Vertical Shaft clamp Fixing Work In Progress









 $Fifth\ Floor-2^{nd}\ Coat\ \ Wall\ Putty\ Work\ In\ Progress$









First Floor – Primer Work In Progress



















External Texture – North Side Work In Progress











Plumbing Shaft – **Primer Work In Progress**








Lift – Painting Work In Progress









External – Entry Entrance Arch Slab Concrete Work Completed










External Plastering – South Side Rough & Final Coat Work In Progress









External Plastering – West Side Final Coat Work In Progress









Compound wall Plastering – North & East Side Work In Progress











OTS & Shaft Plastering Work In Progress

















MOCK UP – Window Installation Work In Progress





Thank you!