



DRA HARMONY

CONSTRUCTION UPDATES – SEPTEMBER-2025

STAGE COMPLETION STATUS UP TO SEPTEMBER-25

S. No	Description	Status	Remarks
1	Completion of Foundation	Completed	
2	Completion of Stilt Floor Roof	Completed	
3	Completion of Upper Stilt Floor Roof	Completed	
4	Completion of First Floor Roof	Completed	
5	Completion of Third Floor Roof	Completed	
6	Completion of Fifth Floor Roof	Completed	
7	Completion of Seventh Floor Roof	Completed	
8	Completion of Ninth Floor Roof	Completed	
9	Completion of Eleventh Floor Roof	Completed	
10	Completion of Thirteenth Floor Roof	Completed	
11	Completion of Masonry Work	Completed	
12	Completion of Internal Plastering	Completed	
13	Completion of Internal Finishes	In Progress	



West side Elevation



East Side Elevation



South Side Elevation



North Side Elevation



Stilt Floor Plastering – Block Work & Plastering Work In Progress



Amenity Block Plastering – Lift & Staircase Work Completed



External Plastering – North Side Work In Progress



OTS Plastering – Work In Progress



**Compound Wall Plastering – North Side Outer & Inner Work
In Progress**



Flooring Tiles – Thirteenth Floor Work Completed



Wall Tiles – Thirteenth Floor Work Completed



Utility Tiles – 10th Floor Work Completed



Corridor Tiles – Seventh Floor Work In Progress



Seventh Floor – Primer Work In Progress



First Coat Painting Work – Upto 5th floor Completed



OTS & Shaft - Primer Work In Progress



OTS & Shaft - Painting Work In Progress



External Texture – South Side Work Completed



External Painting – 1st Coat Work In Progress



Terrace – Press Tiles Laying Work In Progress



Amenity Block – Terrace Headroom Waterproofing Work Completed



Private Terrace – Waterproofing Work In Progress



Plumbing – Stilt Chamber Work In Progress



Storm Water Trench – West Side Wall Completed



UPVC Window – Fixing Work In Progress



Balcony Handrail – Fixing Work In Progress



Door – 4th Floor Fixing Work In Progress



OTS Covering – Fabrication Work In Progress



Shaft Louver – Fixing Work In Progress



External Fire Fighting – Hydrant Line Fixing Work In Progress



Entry Entrance Arch- Plastering Work In Progress

*Thank
you!*