



## DRA HARMONY CONSTRUCTION UPDATES – DECEMBER-2025

## STAGE COMPLETION STATUS UP TO DECEMBER-25

<b>S. No</b>	<b>Description</b>	<b>Status</b>	<b>Remarks</b>
1	Completion of Foundation	Completed	
2	Completion of Stilt Floor Roof	Completed	
3	Completion of Upper Stilt Floor Roof	Completed	
4	Completion of First Floor Roof	Completed	
5	Completion of Third Floor Roof	Completed	
6	Completion of Fifth Floor Roof	Completed	
7	Completion of Seventh Floor Roof	Completed	
8	Completion of Ninth Floor Roof	Completed	
9	Completion of Eleventh Floor Roof	Completed	
10	Completion of Thirteenth Floor Roof	Completed	
11	Completion of Masonry Work	Completed	
12	Completion of Internal Plastering	Completed	
13	Completion of Internal Finishes	In Progress	

# PROGRESS PHOTOS

WEST ELEVATION - PREVIOUS MONTH



WEST ELEVATION - THIS MONTH



# PROGRESS PHOTOS

EAST ELEVATION - PREVIOUS MONTH



EAST ELEVATION - THIS MONTH



# PROGRESS PHOTOS

SOUTH ELEVATION - PREVIOUS  
MONTH



SOUTH ELEVATION - THIS MONTH



# PROGRESS PHOTOS

NORTH ELEVATION - PREVIOUS  
MONTH



NORTH ELEVATION - THIS MONTH



# PROGRESS PHOTOS



**8<sup>TH</sup> FLOOR CORRIDOR COMMON LIGHT FIXING WORK IN PROGRESS**



**UPTO 6<sup>TH</sup> FLOOR CORRIDOR SOAP WASH COMPLETED**

# PROGRESS PHOTOS



CP & SANITARY - 9<sup>TH</sup> FLOOR FIXING WORK IN PROGRESS



ELEVATION HANDRAIL FIXING WORK IN PROGRESS

# PROGRESS PHOTOS



**ELECTRICAL - COMMON AREA LIGHT FIXING WORK IN PROGRESS**



**ELECTRICAL - PANEL ROOM 1 & 2 CABLE GLAND WORK IN PROGRESS**

# PROGRESS PHOTOS



1<sup>ST</sup> COAT EXTERNAL PAINTING WORK COMPLETED



6<sup>TH</sup> FLOOR 2<sup>ND</sup> COAT PAINTING WORK IN PROGRESS

# PROGRESS PHOTOS



**FIRE FIGHTING - STILT FLOOR WORK IN PROGRESS**



**LIFT GRANITE - UPPER STILT LIFT GRANITE WORK COMPLETED**

# PROGRESS PHOTOS



**STILT SCREED CONCRETE WORK 2<sup>ND</sup> PART WORK IN PROGRESS**



**WEST LIFT - RAILING WORK IN PROGRESS**

# PROGRESS PHOTOS



DG EXHAUST WORK COMPLETED



TRANSFORMER YARD - PAINTING WORK COMPLETED

# PROGRESS PHOTOS



**HNS PUMP WORK COMPLETED**



**UG SUMP VENTILATION WORK COMPLETED**

# PROGRESS PHOTOS



**EXTERNAL - WEST SIDE PLUMBING CHAMBER WORK IN PROGRESS**



**EXTERNAL - NORTH SIDE CONSOLIDATION CHAMBER WORK IN PROGRESS**



**EXTERNAL - BOREWELL CHAMBER WORK IN PROGRESS**



**EXTERNAL - ENTRANCE COMPOUNDWALL PLASTERING WORK IN PROGRESS**



# THANKS