



DRA HARMONY
CONSTRUCTION UPDATES – FEBRUARY-2026

STAGE COMPLETION STATUS UP TO FEBRUARY-25			
S. No	Description	Status	Remarks
1	Completion of Foundation	Completed	
2	Completion of Stilt Floor Roof	Completed	
3	Completion of Upper Stilt Floor Roof	Completed	
4	Completion of First Floor Roof	Completed	
5	Completion of Third Floor Roof	Completed	
6	Completion of Fifth Floor Roof	Completed	
7	Completion of Seventh Floor Roof	Completed	
8	Completion of Ninth Floor Roof	Completed	
9	Completion of Eleventh Floor Roof	Completed	
10	Completion of Thirteenth Floor Roof	Completed	
11	Completion of Masonry Work	Completed	
12	Completion of Internal Plastering	Completed	
13	Completion of Internal Finishes	Completed	

PROGRESS PHOTOS

WEST ELEVATION - PREVIOUS MONTH



WEST ELEVATION - THIS MONTH



PROGRESS PHOTOS

EAST ELEVATION - PREVIOUS MONTH



EAST ELEVATION - THIS MONTH



PROGRESS PHOTOS

SOUTH ELEVATION - PREVIOUS MONTH



SOUTH ELEVATION - THIS MONTH



PROGRESS PHOTOS

NORTH ELEVATION - PREVIOUS MONTH



NORTH ELEVATION - THIS MONTH



PROGRESS PHOTOS



UPTO 13TH FLOOR PAINTING WORK COMPLETED



LOBBY 1ST COAT PAINT - UPTO 12TH FLOOR COMPLETED

PROGRESS PHOTOS



STILT FLOOR 2nd COAT PAINTING WORK COMPLETED



STILT FLOOR COLUMN CARD FIXING WORK IN PROGRESS

PROGRESS PHOTOS



STILT FLOOR CAR PARKING MARKING WORK IN PROGRESS



WEST SIDE LIFT COMMENCED

PROGRESS PHOTOS



**EXTERNAL - NORTH SIDE PAVER LAYING COMPLETED AND
CORER PACKING WORK IN PROGRESS**



**EXTERNAL - - EAST SIDE PAVER LAYING COMPLETED AND
CORER PACKING WORK IN PROGRESS**

PROGRESS PHOTOS



EXTERNAL - SOUTH SIDE PAVER LAYING COMPLETED



**EXTERNAL - WEST SIDE PAVER LAYING COMPLETED AND
CORER PACKING WORK IN PROGRESS**

PROGRESS PHOTOS



EXTERNAL STREET LIGHT FIXING WORK IN PROGRESS




EXTERNAL - STP AREA PAVER LAYING WORK IN PROGRESS

PROGRESS PHOTOS



LANDSCAPE WORK - SOIL LEVELING WORK IN PROGRESS



ENTRANCE - GATE PAINTING COMPLETED

PROGRESS PHOTOS



AMENITY BLOCK – FIRST FLOOR INTERIOR WORK IN PROGRESS



AMENITY BLOCK – PAVEMENT PCC AND PLANTER BOX WORK COMPLETED

PROGRESS PHOTOS



AMENITY BLOCK - STARICASE GRANITE WORK COMPLETED



AMENITY BLOCK - KOTA STONE LAYING WORK IN PROGRESS

PROGRESS PHOTOS



STILT FLOOR LETTER BOX FIXING COMPLETED



ENTRANCE - LOGO FIXING COMPLETED

THANKS