



DRA HARMONY
CONSTRUCTION UPDATES – JANUARY-2026

STAGE COMPLETION STATUS UP TO JANUARY-25

S. No	Description	Status	Remarks
1	Completion of Foundation	Completed	
2	Completion of Stilt Floor Roof	Completed	
3	Completion of Upper Stilt Floor Roof	Completed	
4	Completion of First Floor Roof	Completed	
5	Completion of Third Floor Roof	Completed	
6	Completion of Fifth Floor Roof	Completed	
7	Completion of Seventh Floor Roof	Completed	
8	Completion of Ninth Floor Roof	Completed	
9	Completion of Eleventh Floor Roof	Completed	
10	Completion of Thirteenth Floor Roof	Completed	
11	Completion of Masonry Work	Completed	
12	Completion of Internal Plastering	Completed	
13	Completion of Internal Finishes	Completed	

PROGRESS PHOTOS

WEST ELEVATION - PREVIOUS MONTH



WEST ELEVATION - THIS MONTH



PROGRESS PHOTOS

EAST ELEVATION - PREVIOUS MONTH



EAST ELEVATION - THIS MONTH



PROGRESS PHOTOS

SOUTH ELEVATION - PREVIOUS MONTH



SOUTH ELEVATION - THIS MONTH




PROGRESS PHOTOS

**NORTH ELEVATION - PREVIOUS
MONTH**



NORTH ELEVATION - THIS MONTH



PROGRESS PHOTOS



2ND COAT PAINT - UPTO 12TH FLOOR COMPLETED



LOBBY - FIRST COAT PAINTING COMPLETED UPTP 9TH FLOOR

PROGRESS PHOTOS



MAIN DOOR - UPTO 12TH FLOOR COMPLETED & 13TH FLOOR
FIXING WORK IN PROGRESS



CP & SANITARY FIXING UPTO 12TH FLOOR COMPLETED

PROGRESS PHOTOS



1ST COAT EXTERNAL PAINTING WORK COMPLETED



6TH FLOOR 2ND COAT PAINTING WORK IN PROGRESS

PROGRESS PHOTOS




ELECTRICAL - EXTERNAL LIGHT FIXING FIXING WORK IN PROGRESS



ELECTRICAL - COMMON METER CHARGING WORK COMPLETED

PROGRESS PHOTOS



**FIRE FIGHTING - HYDRANT LINE VALVE FIXING WORK
COMPLETED**



**DOUBLE HEIGHT SHAFT PLUMBING LINE WORK IN
PROGRESS**

PROGRESS PHOTOS



PRIVATE TERRACE - LATTICE WORK IN PROGRESS



UPPER STILT WELDED MESH WORK COMPLETED

PROGRESS PHOTOS



STILT FLOOR SHERA PLANK FIXING WORK IN PROGRESS




**INTERNAL & EXTERNAL CCTV CAMERA LINE FIXING
FIXING WORK IN PROGRESS**

PROGRESS PHOTOS



STP - PUMP FIXING FIXING WORK IN PROGRESS



STILT FLOOR SCREED CONCRETE WORK COMPLETED

PROGRESS PHOTOS



AMENITY BLOCK - LIFT GRANITE WORK COMPLETED



AMENITY BLOCK - AC UNIT FIXING COMPLETED

PROGRESS PHOTOS



UPPER STILT 2ND COAT PAINTING COMPLETED



ENTRY RAMP 2ND COAT PAINTING COMPLETED

PROGRESS PHOTOS



EXTERNAL 2ND COAT PAINT WORK IN PROGRESS



BADMINTON COURT CONCRETE COMPLETED

PROGRESS PHOTOS



EXTERNAL - RAINWATER CHAMBER COVER FIXING WORK
IN PROGRESS



EXTERNAL - SOIL CUTTING & LEVELING WORK IN
PROGRESS



EXTERNAL - EAST SIDE GSP WORK IN PROGRESS



EXTERNAL - WEST SIDE CONNECTIN TRENCH WORK IN
PROGRESS



THANKS