# **DRA HARMONY CONSTRUCTION UPDATES – JULY 2024**









STAGE COMPLETION STATUS UP TO JULY 24			
S. No	Description	Status	
1	Completion of Foundation	Completed	
2	Completion of Stilt Floor Roof	Completed	
3	Completion of Upper Stilt Floor Roof	Completed	
4	Completion of First Floor Roof	Completed	
5	Completion of Third Floor Roof	Completed	
6	Completion of Fifth Floor Roof	Completed	
7	Completion of Seventh Floor Roof		
8	Completion of Nineth Floor Roof		
9	Completion of Eleventh Floor Roof		
10	Completion of Thirteenth Floor Roof		
11	Completion of Masonry Work	In Progress	Upto 2 <sup>nd</sup> Floo
12	Completion of Internal Plastering		
13	Completion of Internal Finishes		



Remarks			
oor Completed			
•			





Main Building – Seventh Floor Slab Shuttering & Reinforcement Work In Progress








### Main Building – Seventh Floor Slab Reinforcement Work In Progress







#### **Main Building – Seventh Floor Shuttering Work In Progress**







#### Main Building – Sixth Floor Slab De-Shuttering Work Completed







Fifth Floor– Hacking work & surface grinding work in progress.








#### **Second Floor – Block work Is Completed**







#### **Third Floor – Block work In Progress**







### **Fourth Floor – Block work In Progress**









## Main Building – West Side View










### Main Building–North Side View









### **Main Building– South Side View**







#### Main Building – North West Side View.










### Main building – East side view.









# STP – Wall 2<sup>nd</sup> lift waterproofing & Slab Shuttering Work In Progress







**EXTERNAL TRENCH – Trench Raft & Wall Reinforcement Work In Progress.** 







