



DRA HARMONY

CONSTRUCTION UPDATES – SEPTEMBER 2024



Main Building – Eighth Floor Roof Slab Concrete Work Completed



Main Building – Ninth Floor Column Shuttering Work In Progress



Main Building – Ninth Floor Column Reinforcement Work In Progress




Main Building – Seventh Floor Hacking & Surface Preparation Work In Progress



Main Building –Seventh Floor Block Work In Progress



Main Building –Sixth Floor Block Work Completed



Main Building – First Floor Internal Wall Plastering Work In Progress



Main Building – Second Floor Internal Wall Plastering Work In Progress



Main Building – First Floor Kitchen Counter Slab Work Completed



Main Building – Sixth Floor Button Marking Work In Progress.



Third Floor - Electrical Wall Chasing Work Completed



Fourth Floor - Electrical Wall Chasing Work In Progress



Sixth Floor - AC Sleeve Fixing Work In Progress



STP – Pump Room Slab Concrete Work Completed.



STP – Inner Waterproofing Work In Progress.



Compound wall Type-1 Pardi Wall Shuttering Work In Progress



Compound wall – Type-6 RC Wall Erection Work In Progress



Main Building – West & North Side View.



Main Building –East Side View.



Main Building – West Side View.



Main Building - South Side View.



Main Building - North Side View

*Thank
you!*