






DRA INARA Monthly Construction Updates – February 2025









Villa no 9,10,11 Top View







Villa no 12,13,14 Top View







VillaNo 5 – Second Floor Column concreting work completed







VillaNo 4-FF Bedroom Area Block work completed







Villa No 3 – GF Roof Slab concrete work completed







Villa No 06 – SF Bedroom Blockwork in progress







Villa No 09 – FirstFloor Roof Beam Shuttering work in progress








Villa No 10 – First floor column concrete work completed









Villa No 11 – FF Roof Beam shuttering Work in progress







Villa No 12 – First Floor Roof Slab Reinforcement work in progress







Villa 17 - Ground Floor Slab Shuttering work in progress







Internal Road Kerb Wall Fixing work in progress







Villa No 7, 8 – GF Flooring PCC Pouring work completed







Villa no 16 – South and East Elevation







Villa no 16 – Southwest Corner View







Villa no 20-West Side Elevation









Villa no 20-South side Elevation









Villa no 16 – Southwest Corner View







Internal Road Top view







Internal Road Top view







Internal Road DBM course Laying work completed







Internal Road DBM course Laying work completed







Entrance Arch Front View







Entrance Arch In Side





