



DRA INARA
Monthly Construction Updates – July 2025



Villa No 3- External Scaffolding fixing work in progress



Villa No 3- External Scaffolding fixing work in progress



Villa No 4- Front elevation view




Villa No 4 South side external plastering in work



Villa No 4 , 5 , 6 , 7 , 8 Northeast corner view



Villa No 5 – Front side Elevation view



Villa No 5 – FF bedroom toilet wall tile laying work in progress



Villa No 6 – Front elevation plastering work in progress



Villa No 7- Front Elevation view



Villa No 7- SF Electrical pipeline wall chasing work in progress



Villa No 8 - Front Elevation view



Villa No 8 – SF Bedroom blockwork in progress



Villa No 9 – Front Elevation external plastering work in progress



Villa No 9 – Southside external plastering work in progress



Villa No 10- Front Elevation view



Villa No 10- FF Bedroom internal plastering work in progress



Villa No 11- External scaffolding fixing work in progress



Villa No 11- FF Bedroom Electrical Pipeline laying work in progress



Villa No 8 , 9 , 10 , 11 Backside Elevation view



Villa No 11 , 12 Westside view



Villa No 12 – External plastering work in progress



Villa No 12 – FF Toilet Sunken screed concreting work in progress



Villa No 13 – Head room Roof slab shuttering work in progress



Villa No 13 – FF Bedroom electrical wall chasing work in progress



Villa No 13 – SF Bedroom Blockwork in progress



Villa No 14 – FF Roof slab concreting work completed



Villa No 15 – FF Roof slab concreting work completed



Villa No 17 – SF Roof slab reinforcement work in progress



Clubhouse sub-structure column concreting work completed



South Side Compound wall blockwork in progress



North Side Compound wall internal plastering in progress



Villa 6 - 11 Front elevation view



Villa No 3 - Northwest corner view



Villa No 3- Eastside external wall plastering work in progress



Villa No 4 - External wall primer coat applying work in progress




Villa No 4,5 Northeastcornerview



Villa No 5 - External wall primer coat applying work in progress



Villa No 5 – Backside plumbing shaft pipeline laying work in progress



Villa No 5 – SFbedroomtoilet wall tilelaying work in progress



Villa No 6 - Front Elevation view



Villa No 7- FrontElevationview



Villa No 7- Headroom Electrical pipeline laying work in progress



Villa No 8 - Front Elevation view



Villa No 9 – Front Elevation external plastering work in progress



Villa No 9 – Southside external wall plastering work in progress



Villa No 10- Front Elevation view



Villa No 11- External scaffolding fixing work in progress



Villa No 11- Westside external plastering work in progress



Villa No 8, 9, 10, 11 Backside Elevation view



Villa No 12 – Southwest corner view



Villa No 13 – Head room Roof slab concreting work completed



Villa No 13 – FF Bedroom internal plastering work in progress



Villa No 13 – SF Bedroom Blockwork in progress



Villa No 14 – Front elevation view



Villa No 15 – Front elevation View



Villa No 17 – Front elevation view



North Side Compound wall internal plastering work in progress



South Side Compound wall internal plastering work in progress



North Side Compound wall External plastering in progress



Phase 2 – villa no 51 - pile cap preparation work in progress



Phase 2 – villa no 48 to 51 pile cap preparation work in progress



Villa No 3 – Front Elevation plastering work in progress



Villa No 3- Northsideexternal wall plastering work in progress



Villa No 3- GF Powder toilet screed concrete pouring work completed



Villa No 4 – frontelevation view




Villa No 4 – Backside plumbing Shaft Shera plank fixing work in progress





Villa No 4,5 Northeast corner view



Villa No 5 - Front Elevation view



Villa No 5 – Westside outer wall Pebble texture paying work in progress



Villa No 5 – SF bedroom toilet wall tile laying work in progress



Villa No 5 – SF bedroom flooring tile laying work in progress



Villa No 6- FrontElevationview



Villa No 6, 7, 8, 9 Headroom backside view



Villa No 7- FrontElevationview



Villa No 7- FF Bedroom Internal plastering work in progress



Villa No 8 - Front Elevation view



Villa No 8 - FF bedroom internal plastering preparation work in progress




Villa No 9 –Front Elevation view



Villa No 9 – SF bedroom toilet wall tile laying work in progress



VillaNo 10- Front elevation plastering preparation work in progress



VillaNo 10- Westside external wall 1st coat rough plastering work in progress



Villa No 11- Front elevation plastering work in progress



Villa No 11- Westside external plastering work in progress



Villa No 12 – External wall primer coat applying work in progress



Villa No 13 – Front elevation view



Villa No 13 – FF Bedroom internal plastering work in progress



Villa No 13 – SF Bedroom block work in progress



Villa No 14– Front elevation view



Villa No 14– Ground floor blockwork in progress



Villa No 15 – Front elevation View



Villa No 15 – Ground floor blockwork in progress



Villa No 17 – Front elevation view



Phase 1 - South Side Compound wall internal plastering work in progress



Phase 2 - Southside Ccompound RCC wall shuttering work in progress



Phase 2 – villa no 48 to 51 pile cap levelling course PCC pouring work completed



Phase 2 – villa no 46 - pile cap preparation work in progress



Villa No 3 – Front Elevation view



Villa No 3- Northside plumbing shaft pipeline laying work in progress



Villa No 4 – front elevation view



Villa No 4 – Terrace area M.S Pecola fixing work in progress



Villa No 6 – 11 headroom area plastering work in progress



Villa No 4,5 Northeast corner view



Villa No 5 - Front Elevation view



Villa No 5 – North side external wall pebble texture applying work in progress



Villa No 5 – FF Bedroom Flooring tile laying work in progress



Villa No 5 – FF bedroom tile protection work after tile laying



Villa No 6- FrontElevationview



Villa No 6 – Terrace area M.S Percola fixing work in progress



Villa No 7- FrontElevationview



Villa No 7- FF Bedroom Internal plastering work in progress



Villa No 7- Westside external wall 2nd coat plastering work in progress



Villa No 7- FF lift elevation blockwork in progress



Villa No 8 - Front elevation view



Villa No 8 - FF bedroom internal plastering work in progress



Villa No 9 –Front Elevation view MS ‘C’ Channel fixing work in progress



Villa No 9 – FF bedroom toilet wall tile laying work in progress



Villa No 9 – Terrace area MS Percola fixing work in progress



Villa No 10- Front elevation plastering preparation work in progress



Villa No 11- Front elevation plastering work in progress



Villa No 11- Westside external plastering work in progress



Villa No 12 – External wall pebble texture applying work in progress



Villa No 12 – External wall pebble texture applying work in progress



Villa No 13 – Front elevation view



Villa No 13 – SF Bedroom Electrical pipeline laying work in progress



Villa No 14– SF column concreting work completed



Villa No 14 – Ground floor blockwork in progress



Villa No 15 – SF Column concreting work completed



Villa No 15– Ground floor blockwork in progress



Villa No 17 – FF Bedroom blockwork in progress



Phase 1 - Northside compound wall external plastering work in progress



Phase 2 - Southside compound RCC wall concreting work in progress



Phase 2 – villa no 53 Earth work for pile cap pcc preparation work in progress

*Thank
you!*