



DRA INARA
Monthly Construction Update Progress Photos – September 2025



Villa No 3-Front Elevation View



Villa No 3 Terrace Brick Bat Coba Laying Work In Progress



Villa No 3 FF 2nd Coat Putty Work Completed



Villa No 4 - Front Elevation View



Villa No 4 & 5 Side Elevation view




Villa No - 5 Front Elevation view



Villa No - 5 Wire Pulling Work Progress



Villa No 6- Front elevation View



Villa No 6- Terrace Clay Tiles Laying Completed



Villa No 7-Front elevation MS Pergola Fixing Work Completed



Villa No 7-Staircase Granite Laying Work Completed



Villa No 8- Front elevation MS Pergola Fixing Work Completed



Villa No 9 –Front Elevation View



Villa No 9 –FF Bed Room Tiles Laying Work Completed



Villa No 10 –Front Elevation View



Villa No 7 To 11 –Front Elevation Top View



Villa No 11-Front elevation MS Pergola Fixing Work Completed



Villa No 12- Front Elevation Slate Tiles Laying Work In Progress



Villa No 13- Front Elevation Slate Tiles Laying Work In Progress



Villa No 13 to 15 Elevation Top View



Villa No 14 – Front Elevation Head Room Concrete Pouring Completed



Villa No 15–Front Elevation Head Room Concrete Pouring Completed



Villa No 15–SF Block Work In Progress



Villa No-17 Front Elevation Head Room Concrete Pouring Completed



Villa No-17 Side Elevation View



Phase 2 – villa no 50 Basement DPC Work In Progress



Phase 2 – villa no 47&48 Basement Block Work Completed



Phase 2 – villa no 68 Plinth Beam Reinforcement Work In Progress



Phase 2 – villa no 69 Pile Cap Concrete Completed



Phase 2 – villa no 74 Plinth Beam Shuttering Work In Progress



Phase 2 – villa no 75 Plinth Beam Reinforcement Work In Progress



Phase 2 – villa no 80 Pile Cap Shuttering Work In Progress



Phase 2 – villa no 68 Pedestal Column Shuttering Work Progress



Villa No 3-Front Elevation View



Villa No 3 Terrace Area Clay Tiles Laying Completed



Villa No 3 Staircase Granite Laying Completed



Villa No 3 Wire Rope Pulling Work In Progress



Villa No 3 To 5-Side Elevation View



Villa No 4 - Front Elevation View



Villa No 4 & 5 Side Elevation view



Villa No - 5 Front Elevation view



Villa No – 5 Putty Scraping Work In Progress



Villa No - 5 Compound Wall Block Work In Progress



Villa No 6- Front elevation View



Villa No 7-Front elevation View



Villa No 8- Front elevation View



Villa No 9 –Front Elevation View



Villa No9 –Terrace Area Clay Tiles Laying Completed



Villa No 10 –Front Elevation View



Villa No 10 –Staircase Granite Laying Completed



Villa No 5 To 11 –Side Elevation Top View



Villa No 4 To 9–Front Elevation Top View



Villa No 11-Front elevation View



Villa No 12- Front Elevation View



Villa No 13- Front Elevation Slate Tiles Laying Work Completed



Villa No 13 to 15 Elevation Top View



Villa No 14 – Front Elevation View



Villa No 15–Front Elevation View



Villa No 15–SF Block Work In Progress



Villa No-18&19 Club House Footing Reinforcement Working Progress



Villa No-18&19 STP RCC Wall Shuttering Working On Progress



Phase 2 Compound Wall Shuttering Working On Progress



Phase 2 Compound Wall Block Work On Progress



Phase 2 – villa no 53 Basement DPC Work Completed



Phase 2 – villa no 48 GF Column Concrete Pouring Completed



Phase 2 – villa no 57 Basement Block Work Completed



Phase 2 – villa no 60 Pedestal Column Concrete Completed



Phase 2 – villa no 73 Basement Block Work Completed



Phase 2 – villa no 69 Plinth Beam Shuttering Work In Progress





Phase 2 – villa no 74 Pedestal Column Concrete Completed



Phase 2 – villa no 77 Plinth Beam Reinforcement Work In Progress



Villa No 3-Front Elevation View



Villa No 3-Window Fixing Work Progress



Villa No 3-Compound Wall Plinth Beam Shuttering Work In Progress



Villa No 3- Toilet Ledge Wall Threshold Granite Fixing Completed



Villa No 3 To 5-Side Elevation View



Villa No 4 - Front Elevation View



Villa No 4-Window Fixing Work Progress



Villa No 4 - Second Coat Putty Scraping Completed



Villa No 4 & 5 Side Elevation view



Villa No - 5 Front Elevation view



Villa No -5 Window Fixing Work Progress



Villa No 6- Front elevation View



Villa No 7-Front elevation View



Villa No 7-GF Flooring Tile Laying Work Completed



Villa No 8- Front elevation View



Villa No 9 –Front Elevation View



Villa No 9 – Electrical Wire Pulling Work On Progress



Villa No 10 –Front Elevation View



Villa No 7 To 11 –Side Elevation Top View



Villa No 4 To 9–Front Elevation Top View



Villa No 11-Front elevation View



Villa No 11-SFToilet Soil and Waste Line Pipe Laying Work On Progress.



Villa No 12- Front Elevation View



Villa No 12- Terrace Clay Tiles Laying Work Completed



Villa No 13- Front Elevation View



Villa No 14 – Front Elevation View



Villa No 15–Front Elevation View



Villa No 17 –East Side External Plastering Work In Progress



Villa No 17–South Side External Plastering Work In Progress



Villa No-18&19 Club House Lift Pedestal Column Concrete Completed



Villa No-18&19 STP RCC Wall Concrete Pouring Completed



Phase 2 Compound Wall Block Work On Progress



Phase 2 – villa no 49 GF Roof Slab Shuttering Work In Progress



Phase 2 – villa no 68 Basement Block Work Progress



Phase 2 – villa no 56 DPC Work Completed



Phase 2 – villa no 58 Basement Block Work Completed



Phase 2 – villa no 69 Plinth Beam Concrete Completed



Phase 2 – villa no 51 GF To Mid landing Staircase Reinforcement Work In Progress



Villa No 3-Front Elevation View



Villa No 4 - Front Elevation View



Villa No 4 &5&6 Side Elevation view



Villa No - 5 Front Elevation view



Villa No - 5 Solar Panel Fixing Work On Progress



Villa No 6- Front elevation View



Villa No 6-Compound Wall Plastering Work In Progress



Villa No 6- Solar Panel Channel Fixing Work On Progress



Villa No 6- Putty Scrapping Work On Progress



Villa No 7-Front elevation View



Villa No 7-Terrace Area Clay Tiles Laying Completed



Villa No 8- Front elevation View



Villa No 8-FF&SF Toilets Tiles Laying Work In Progress



Villa No 9 –Front Elevation View



Villa No 9 –Aluminium Louvers Fixing Work On Progress



Villa No 10 –Front Elevation View



Villa No 10 –Terrace Area Waterproofing Protective Plastering Work Completed.



Villa No 7 To 11 –Side Elevation Top View



Villa No 11-Front elevation View



Villa No 12- Front Elevation View



Villa No 13- Front Elevation Primer work in Progress



Villa No 13-SFToilet Soil and Waste Line Pipe Laying Work On Progress.



Villa No 13- FF &SF Wall 1st Coat Putty Work In Progress



Villa No 14 – Front Elevation View



Villa No 15 – Front Elevation View



Villa No 17–East Side External Plastering Work Completed



Villa No 17–South & North Side External Plastering Work In Progress



Villa No-18&19 Club House Plinth Beam Concrete Completed



Villa No-18&19 STP RCC Wall Cover Salb Shuttering Work In Progress



Phase 2 Compound Wall Block Work On Progress



Phase 2 Compound Wall Plastering Work On Progress



Phase 2 – villa no 49 GF Roof Slab Shuttering Work In Progress



Phase 2 – villa no 75 Basement DPC Work In Progress



Phase 2 – villa no 78 Plinth Beam Shuttering Work In Progress



Phase 2 – villa no 79 Plinth Beam Reinforcement Work In Progress



Phase 2 – villa no 71 Plinth Beam Shuttering Work In Progress



Phase 2 – villa no 51 GF Roof Slab Shuttering Work In Progress

*Thank
you!*