



DRA INARA CONSTRUCTION UPDATES – AUGUST 2024



Villa No 3 – Front Elevation Slate tile laying work in progress



Villa No 3- Northside External wall pebble texture applying work in progress



Villa No 3- SF Bedroom 1st coat wall putty applying work in progress



Villa No 3- Terrace area M.S Percola fixing work in progress



Villa No 4 – Front Elevation Slate tile laying work in progress



Villa No 4 – Car parking area Slate tile laying work in progress



Villa No 4 – Terrace area M.S Pecola fixing work in progress



Villa No 4 – Terrace area vox false ceiling fixing work in progress



Villa No 4 – External wall pebble texture 1st coat colour applying work in progress



Villa No 4, 5 Front Elevation view



Villa No 6 – 11 headroom area backside view



Villa No 5 -11, Top Elevationview



Villa No 5 -11, Front Elevation view



Villa No 5 – SF Balcony Elevation slate tile laying work in progress



Villa No 5 – Northside external wall pebble texture applying work in progress



Villa No 5 – Terrace area M.S Percola enamel applying work in progress



Villa No 5 – Terrace area false ceiling fixing work in progress



Villa No 5 – Terrace area Brickbat Cob laying work in progress



Villa No 5-6 External wall 1st coat colour paint applying work in progress



Villa No 6- Front elevation wall pebble texture applying work in progress



Villa No 6- FF Bedroom toilet wall tile laying work in progress



Villa No 6- FF Bedroom toilet wall tile laying work in progress



Villa No 6 – Terrace area M.S Percola enamel applying work in progress



Villa No 6 – Terrace area vox false ceiling fixing work in progress



Villa No 7- Front Elevation wall plastering preparation work in progress



Villa No 8- Front elevation wall plastering work in progress



Villa No 9 –Front Elevation pebble texture applying work in progress



Villa No 9 – FF bedroom flooring tile protection work after tile laying



Villa No 9 – Terrace area MS Percola fixing work in progress



Villa No 9 – Terrace area MS Percola fixing work in progress



Villa No 9 – Backside elevation 1st coat colour painting work in progress



VillaNo 10- Front elevation external primer applying work in progress



VillaNo 10- Terrace area M.S Percola fixing work in progress



VillaNo 10- Backside external primer coat applying work in progress



Villa No 11- Front elevation Archi concrete putty applying work in progress



Villa No 11- Westsideview



Villa No 07- 11 ,Backside Elevation view



Villa No 12 – External wall pebble texture applying work in progress



Villa No 12 – Terrace area M.S Percola fixing work in progress



Villa No 13 – Front projection slab blockwork in progress



Villa No 13 – SF Bedroom Internal plastering work in progress



Villa No 14 – SF Roof slab concreting work completed




Villa No 14 – FF Bedroom blockwork in progress



Villa No 15– SF Roof slab shuttering work in progress



Villa No 15– First Floor blockwork in progress



Villa No 15 – Headroom column concreting work completed



Villa No 17 – FF Bedroom blockwork in progress



Villa No 17 – SF Bedroom blockwork in progress



Villa No 18 – STP wall 1st lift concreting work completed



Phase 1 - Southside compound External plastering work in progress



Phase 2 - Southside compound wall blockwork in progress



Phase 2 – villa no 50, 51 plinth beam pcc concrete pouring work in progress



Phase 2 – villa no 53 pile cap pcc concrete pouring work in progress



Phase 2 – villa no 54 pile cap concrete chipping work in progress



Phase 2 – villa no 67 , 68 pile cap concrete chipping work in progress



Villa No 3 – Front Elevation Slate tile laying work Completed



Villa No 3- Northsidewall Side Elevation View



Villa No 3- FF Toilet wall Tile Laying work in progress



Villa No 3- SFBedRoomWallPuttyApplyingworkin progress



Villa No 4 – Front Elevation Slat tile laying work Completed



Villa No 4 – Treece Area Brick Bad Coba laying work in progress



Villa No 4, 5 Front Elevation view



Villa No 5 Front Elevation view



Villa No 5 – Treece area weathering course Completed



Villa No 5 Staircase Granite Laying Work Completed



VillaNo 6 GF Flooring Tiles Laying Work Completed



Villa No 6 Staircase Granite Laying Work Progress



Villa No 6- Front elevation wall pebble texture applying work in progress





Villa No 7- Front Elevation plastering work in progress



Villa No 8- Front elevation wall plastering work Completed



Villa No 9 –Front Elevation MS Channel Primer applying work in progress



VillaNo 10- FF Toiletwall Layingwork Completed



Villa No 11 to 6- Side elevation View



Villa No 11-Front elevation primer applying work in Completed



Villa No 12- FF&SF Toilet wall Laying work Completed



Villa No 13-Front elevation Plastering Preparation work in Progress



Villa No 15–SF Roof Slab Shuttering Work In Progress



Villa No 15 – FF Block Work Completed



Villa No-17 Front elevation View



Villa No-17 SF Block Work In Progress



Villa No-17 GF Plastering Work Completed



Villa No 18 – STP wall 2nd lift concreting work completed



Phase 2 - Southside compound wall Plastering work in progress



Phase 2 – villa no 50, 51 plinth beam concrete pouring Completed



Phase 2 – villa no 49 plinth beam concrete pouring Completed



Phase 2 – villa no 52 plinth beam PCC Concrete pouring Completed



Phase 2 – villa no 53 Column Reinforcement work in progress



Villa No 3 – Front Elevation Slate tile laying work Completed



Villa No 3- FF Toilet Tile Laying work Completed



Villa No 3- Wall Putty Applying work Completed



Villa No 3- MS Pergola False ceiling work Completed



Villa No 4 – Front Elevation Staircase Painting work Completed



Villa No 4 – Staircase Granite Laying Work Completed



Villa No 4 , 5 Side Elevation view



Villa No 5 Front Elevation view



Villa No 5 ; Tracee Screed Concrete Completed



Villa No 6- Front elevation Slate Tiles Laying Work Completed



Villa No 7- Front Elevation plastering work Completed



Villa No 8-Front elevation primer applying work in Completed



Villa No 9 –Front Elevation Slate Tiles Laying work in progress



Villa No 10 –Front Elevation Slate Tiles Laying work in progress




Villa No 7 To 11 –Front Elevation Top View



Villa No 11-Front elevation Arch Concrete Putty Applying Work Progress



Villa No 12-Front Elevation View



Villa No 12- Staircase Granite Laying Work Completed



Villa No 12- GF Toilet Tiles Laying Work Completed



Villa No 13-Front elevation Plastering work in Progress



Villa No 13- OHT Tank Shuttering work in Progress



Villa No 14 – Front Elevation View



Villa No 14 –FF Block Work Completed



Villa No 15 –SF Roof Slab Concrete Completed



Villa No 15 –FF Plastering Work in Progress



Villa No-17 Front elevation View



Villa No-17 SF Block Work Completed



Villa No-17 FF Plastering Work In Progress



Villa No 18 – STP wall External Area Waterproofing work completed



Villa No 18–UG Sump Concrete work completed



Phase 2 – North West compound wall Shuttering & Concrete pouring in Progress



Phase 2 – villa no 50, 51 Basement Block Work Completed



Phase 2 – villa no 49 Basement Block Work Progress

*Thank
you!*