




DRA INARA
Monthly Progress Photos –March 2026– Phase 1



Villa No 3 –Front Elevation View



Villa No 4 –Front Elevation View




Villa No 5 –Front Elevation View



Villa No 6 –Front Elevation View



Villa No 7 –Front Elevation View



Villa No -8 Front Elevation View



Villa No 9 - Front Elevation View




Villa No 10 – Front Elevation View



Villa No 11- Front Elevation View



Villa No 12 –Front Elevation View



Villa No 13- Front Elevation View



Villa No 14 – Front Elevation View



Villa No 15 –Front Elevation View



Villa No 17 –Front Elevation View



Villa No 18&19 – Club House Front Elevation View

*Thank
you!*



DRA INARA
Monthly Progress Photos –March 2026– Phase 2



Villa No 47 –Head Room Slab Concrete Pouring Completed



Villa No 48 –Parapet Wall Block Work In Progress



Villa No 49- Parapet Wall Column Reinforcement Work In Progress



Villa No 50- Head Room Slab Concrete Pouring Completed



Villa No -51 GF&FF Block Work In Progress



Villa No 52 –FF Block Work In Progress



Villa No-53 Head Room Roof Slab Concrete Pouring Completed



Villa No 54 – Head Room Roof Salb Concrete Pouring Completed



Villa No 55- Head Room Roof Slab Concrete Pouring Completed



Villa No 56 – FF Block Work In Progress



Villa No 57- Head Room Roof Slab Concrete Pouring Completed



Villa No 58 –Head Room Roof Slab Concrete Pouring Completed



Villa No 59 –Head Room Roof Slab Shuttering Work In Progress



Villa No 60 – Head Room Roof Slab Shuttering Work In Progress



Villa No 61 –Head Room Roof Slab Shuttering Work In Progress



Villa No 62–GF Column Concrete Pouring Work Completed



Villa No –63 FF Roof Slab Concrete Pouring Completed



Villa No-64 FF Roof Slab Concrete Pouring Completed



Villa No-65 FF Roof Slab Concrete Pouring Completed



Villa No 66–FF Roof Slab Concrete Pouring Completed



Villa No 67 –Head Room Roof Slab Concrete Pouring Completed



Villa No 68–Head Room Roof Slab Concrete Pouring Completed



Villa No 69 –Head Room Roof Slab Concrete Pouring Work Completed



Villa No 70–SF Column Reinforcement Work In Progress



Villa No 71 – FF Roof Slab Concrete Pouring Completed



Villa No 72 –GF Column Concrete Pouring Completed



Villa No 73 – External Plastering Work In Progress



Villa No 74 – External Plastering Work In Progress



Villa No 75 –Parapet Wall Block Work In Progress



Villa No 76 –FF Block Work In Progress



Villa No 77 –GF Block Work In Progress



Villa No 78–FF Roof Slab concrete Pouring completed



Villa No 79 –FF Column Concrete Completed



Villa No 80 –GF Roof Slab Reinforcement Work In Progress



Villa No 81– GF Roof Slab Shuttering Work In Progress

*Thank
you!*



DRA INARA
Monthly Progress Photos –March 2026– Phase 3



Villa No 22 –FF Roof Slab Reinforcement work In Progress



Villa No 23 –GF Roof Slab Shuttering Work In Progress



Villa No 24- GF Roof Slab Reinforcement work In Progress



Villa No 25- FF Column Concrete Pouring Work Completed



Villa No 26- FF Roof Slab Shuttering Work In Progress



Villa No 27 –SF Roof Slab Shuttering Work In Progress



Villa No 28 –FF Block Work In Progress



Villa No-29 Head Room Column Concrete work Completed



Villa No 30 – GF Block Work In Progress



Villa No 31-FF Column Reinforcement Work In Progress



Villa No 32 –FF Column Reinforcement Work In Progress



Villa No 33- FF Column Reinforcement work Completed



Villa No 34 – Plinth Beam Reinforcement Work In Progress



Villa No 35 –Plinth Beam Reinforcement Work In Progress



Villa No 36–GF Column Concrete work Completed



Villa No 37 –FF Roof Slab Reinforcement Work In Progress



Villa No 38–GF Block Work In Progress



Villa No 39 –Head Room Slab Shuttering Work In Progress



Villa No 40–Head Room Slab Shuttering Work In Progress



Villa No 41- FF Roof Slab Reinforcement work Progress



Villa No 42 –FF Roof Slab Concrete Pouring Completed



Villa No 43- FF Column Concrete Work Completed



Villa No 44 –FF Block Work In Progress



Villa No 45–FF Block Work In Progress



Villa No 46–FF Column Reinforcement Work Completed



Villa No 62-GF Roof Slab Shuttering Work In Progress



Villa No 83 & 84–Basement Block Work In Progress



Villa No 85 & 86–Basement Block Work In Progress



Villa No 87–Basement Backfilling Work In Progress



Villa No 88 & 89–GF Column Reinforcement Work In Progress



Villa No 90 & 91–GF Column Reinforcement Work In Progress



Villa No 92&93–GF Column Reinforcement Work In Progress



Villa No 94 to 98–GF Roof Slab Shuttering Work In Progress



Villa No 99 to 102–FF Column Concrete Pouring Completed



Villa No 103–Basement Back Filling Work Completed



Villa No 104–Basement Back Filling Work Completed



Villa No 106–GF Column Reinforcement Work Completed



Villa No 107–Basement Block Work Completed



Villa No 108–FF Column Concrete Pouring Completed



Villa No 110–Footing Shuttering Work In Progress



Villa No 111–Footing Shuttering Work In Progress



Villa No 112–Footing Shuttering Work In Progress



Villa No 113–Basement Block Work Completed



Villa No 114-GF Roof Slab Shuttering Work In Progress



Villa No 115–Basement Block Work Completed



Villa No 116–Plinth Beam PCC Concrete Pouring Completed



Villa No 117–Plinth Beam PCC Dressing Work In Progress



Villa No 118–Basement Back Filling Work Completed



Villa No 119–GF Column Concrete Pouring Work Completed



Villa No 120–GF Roof Slab Shuttering Work In Progress



Villa No 121–Plinth Beam Reinforcement Work In Progress



Villa No 122–Plinth Beam Concrete Pouring Completed



Villa No 123–Plinth Beam Concrete Pouring Completed

*Thank
you!*



DRA INARA
Monthly Progress Photos –March 2026– Phase 4



Villa No 33 –FF Column Reinforcement work Completed



Villa No 35- Plinth Beam Reinforcement work Completed



Villa No 41- FF Roof Slab Reinforcement work Progress



Villa No 43- FF Column Concrete Work Completed



Villa No 82 – Pile Cap Concrete work Completed



Villa No 105 – Basement Back Filling Work In Progress

*Thank
you!*