



DRA INFINIQUE
CONSTRUCTION UPDATES SEPTEMBER -25



North Side View



South Side View.



Front view.



101 Mock up flat finishing work completed.



101 Mock up flat finishing work completed.



102 Sales Office flat finishing work in progress.



2nd floor inner wall plastering work completed.



2nd Floor corridor inner plastering work in progress.



Third floor inner wall plastering work in progress.



Third floor inner wall plastering curing work in progress.



5th Floor block work completed.



6th Floor block work in progress..



7th Floor block work in progress.



8th Floor roof slab shuttering work completed.



8^h Floor roof slab reinforcement work completed.



8th Floor roof slab electrical conduit laying work completed.



8th Floor roof slab concrete laying work completed.



9^h Floor column concrete work completed.



9th Floor roof shuttering work completed.



9th Floor roof concrete work completed.



9th Floor roof curing work in progress.



10th floor roof shuttering work completed .



10th floor roof electrical conduit laying work completed.



10th floor roof concrete work completed .



10th floor column reinforcement work completed.



11th floor column reinforcement work in progress.



11th floor column box fixing work in progress.




Tower -2 P2 Basement roof curing work completed .



Tower -2 Stilt floor column concrete work completed.



Tower -2 stilt floor roof shuttering work completed .



Tower -2 stilt floor roof reinforcement & PT works completed .



Tower -2 stilt floor roof slab concrete work completed .



Tower -2 stilt floor roof slab curing work in progress.

*Thank
you!*