

DRA POLARIS

Construction Updates Photos – August 2024








Filling work 1st level completed







Soil core test has been done.








Fencing work for the street alignment has been completed.









Existing Foundation demolition work in progress









Existing Foundation demolition work in progress









Existing Foundation demolished & debris removed from site.









Sales Office Marking and Excavation work completed.











Sales Office Consolidation and PCC work completed.









Sales Office Plinth beam Reinforcement Cutting and Bar bending work









Sales Office Plinth beam Reinforcement & Shuttering work completed.









Sales Office Concrete & De-shuttering work completed.







Sales office 1st Half fabrication and Electrical work in progress







Sales office 1st Half Panelling and False ceiling channel work in progress







Sales office 1st Half False ceiling work completed and painting work in progress.









Sales office 1st Half painting work in progress.







Sales office 2nd Half Refabrication work in progress







Sales office 2nd Half Refabrication work & Wiring work completed.







Sales office 2nd Half Wall Panelling work completed.









Pillar box has been shifted from Inside the site to Outside for Site Access.





Thank you!