

DRA POLARIS CONSTRUCTION UPDATE PHOTOS – MAY 2026



North side elevation



South side elevation



East side elevation



West side elevation



Main building – 8th floor Roof Slab concrete completed



Main building – 8th floor roof slab Concrete work completed



Main building – 9th floor column reinforcement work completed



Main building – 9th floor column shuttering work completed



Main building – 9th floor column concrete work completed



Main building – 9th floor slab shuttering work in progress



Main building – 9th floor slab reinforcement work in progress



Main building – 9th floor column reinforcement work completed



Main building – 9th floor column shuttering work in progress



Main building – 9th floor column concrete work in progress



Main building – 6th floor block work in progress



Main building – 4th floor wall chasing & pipe fixing work in progress



Main building – 3rd floor internal plastering work in progress



*Thank
you!*